## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	_ Located In:	Corner Code #									
1. Public Land Survey	T R										
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	S 28 T 46N R 30W S T R S 28 T 46N R 30W S T R S T R	SMC west of F10 (GCDB 326240) F10 (GCDB 340240)	Re	gister of	Deeds S	Stamp (	& Fîle	e Nun	nber		
4. Lot No. , Red 5. Private Claims	corded Plat		ı A B	CD	E F	G	Н-	I J	rκ	L	М
above were in conformance with reinstructions of the United States I a Court of Law and /or that the content the rules of the Michigan Board re-established, monumented, recover NOTE: Not more than 2 corn on this certificate.	74, Michigan P.A. of 1970, the corner pregulations and rules therefore as require Department of the Interior, Bureau of La orner points mentioned in lines 3, 4 and d of Land Surveyors or by a Decree ered, found as expressed below:  ers, all in the same town and range,	ed in the current manual of survey and Management or by a decree of 5 above were in conformance with of a Court of Law; established, may be recorded	5 6 —18 7	2	7 1	5	10-		3-5-5-	-12 -13 -24 -25	
A. Description of original mo	onument and accessories and/or s	subsequent restoration:				_					

(F10) Center of Section 28. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

the E-W 1/4 line of Section 28. Corner not established in the original survey.

(SMC) Found a 1/2" diameter rebar with plastic cap stamped "ECI 44283 30097" on the E-W 1/4 line of Section 28, near the east shore of Grant Lake. 1/4 corner E10 is 1966.05' west and Center of Section is 645.45' east. Accepted same as a careful and faithful determination of the position of the corner. The monument does not occupy the position of the OHWM, but is set back east of the true SMC position.

(SMC west of F10) Special Meander corner on the east shore of Grant Lake at its intersection with

(F10) At the intersection of straight lines connecting opposite 1/4 corners of Section 28, I found a 1/2" dia. rebar with plastic cap stamped "ECI 44283 30097" and accepted same as a careful and faithful establishment of the position of the corner. From the position thus established I found a 1"dia. iron pin N23°W 17.4' distant, not accepted as marking the position for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(SMC) Found 1/2" rebar with plastic cap #44283 and (F10) Found 1/2" rebar with plastic cap #44283 and #30097. Set measuring nail with MDNR tag in the #30097. Set measuring nail with tag in the side side of: of the following trees: 3" Maple N65°E 1.9' mrkd "SMC BT" 10" Sugar S29°E 15.95' scribed blazes 5" Maple S63°E 15.5' 10" Maple S41°W 20.7' do do 7" Balsam S07°W 10.8' ďО 9" Maple N15°W 3.75' do 3" B.Spruce S48°W 19.65' 12" Sugar N82°W 16.4' do overgrown blazes Squared a 4" Balsam 1.2' westerly. Set sq'd cedar post adjacent. E= 7918048.830 N= 175258.776 E= 7917852.139 N= 175260.595

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010. (Coord. Ref.=NGS PID AA8080: N= 192972.689 m. E= 7925456.741 m.	00 dativ
Signed by Stephen J Synophisch Date 08/11/2015	STEPHAN J.
Surveyor's Michigan License No. 33986  For the Michigan Department of Natural Resources, Forest Resources Division	SZYSZKOSKI LAND SURVEYOR

FORM APPROVED BY MICHIGAN STATE BOARD & PAGE STORES OF STATE BOARD & PAGE STORES

Jan., 1983