COMMISSION

JOB	NUMBER: 93300	LAND COR	NER RECORDATION CERT	TIFICATE				
	ET NO. : 1-407	Filing Requ	irement of Act 74, Mich. F	P.A. 1970	35	73 E		
۲o	r corners in		1		2.27	7 28 2	MARO	
	MARQUETTE (County)	Located In:	Corner Code ##		1777 TA	DEC 1	. <u>.</u>	
1.	Public Land Survey	T <u>47N</u> R <u>27W</u> T <u>47N</u> R <u>28W</u> T R T R	A-12 M-12		S. S.	FOR TO		
2.	Property Controlling in Section	S T R S T R		LIBER	1	(2)	-<	
3.	Miscellaneous Property in Sec.	S T R S T R			of Deeds S	tamp & File Nu	mber	
		Recorded Plat			всрі	EFG HI	JKLM	
٥.	Private Claims			2	- 6 5	-4-3-	2-1-	
	•			3				
				4	- 7 8	- 9	1112	
		, in a field survey on <u>Tuesday</u> guirements of P.A. 74, Michigan P.		lioned	 			
ín	lines 1 and 2 above were in	n conformance with regulations	and rules therefore as required	in the	1817	—1'6——1' 5——	14-13-	
		uctions of the United States Dep a Court of Law and/or that the cor	•	i Lailu – m		1 1 1		
ab	above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a				20-		23-24-	
Court of Law; established, re-established, monumented, re-monumented, recovered expressed below:			e-monumentea, recoverea, ioui	no as	_3029	_2827	26-25-	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded				11-			1 1 1	
	on this certificate.			12	-3132	33-34	35-36-	
Α.	Description of original	monument and accessories a	nd/or subsequent restoration	13 Ļ n:			<u></u>	
	A-12: Quarter Corner common to Section 31, T47N-R27W and No date given- Marquette County Road Commission field book Section 36, T47N-R28W. 1846: Austin Eurt's original survey #512 indicates a post at a fence intersection.							
	notes describe the corner monument as a Cedar post No corner accessories given.							
	referenced by: 6* Spruce S50W, 5	1						
	(No Species) N35E, 9				•			
	, , , , , , , , , , , , , , , , , , ,							
В.	Description of corner e	Description of corner evidence found and/or method applied in restoring or reestablishing corner:						
	1993 - Set spike in center of old rotted and broken off fence corner post and strands of barbed wire to North and West. The point to this fence post is in good condition. Replaced the corner fence post with a Marquette County Survey Monument. Peer group ratification 12-20-93.							
					•			
				-			1	
	•							
	•						۵	
							•	
_				costing the po	sition of the	corper:		
C.		ent for corner and accessorie						
		ameter aluminum pipe capped wentify the corner referenced		um tablet Marq	uette County	Survey		
	4" Black Spruce N66W		by mails in:			The state of the s		
	10" White Birch N36E					THE UN MICHIE	A.S.	
	6" Black Spruce N84E				#	GERALD W	Nx x	
	6" Black Spruce S47W	20.12 ft. ground in swampy Spruce wood	ls.		#¥/	CARLSON	1+1	
	Bk. 5, Pg. 4	and an anampy abrace wood	···········		8*1	SURVEYOR	 *	
	-				I <u>E</u> I	No.	138	
			i		A SE	24589		
	1 A	11. (1 1 2 2	S S	OFESSIONAL.		
Sic	gned by Must	da Corlson	Date	2-28-7	>	ADDITED !		
	rveyor's Michigan Licens			EUSM TODGUNGU DA	/ MICHIGAN STATE R	OARD OF LAND SURVEYO	RS, JAN. 28, 1971	
Ju				- Anna Williamston Br		REVI	SED MAY 14, 1975 EVISED JAN., 1983	