LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #	Ø
1. Public Land Survey	T 50N R 28	GCDB 200640)	
2. Property Controlling in Section	S 8 T 50N R 28 S T R	9 (GCDB 260540)	i.
3. Miscellaneous Property in Sec.	S T R S T R		
4. Lot No. , Red 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number
above were in conformance with a instructions of the United States if a Court of Law and /or that the court of Law and /or the cour	74, Michigan P.A. of 1970, the or regulations and rules therefore as Department of the Interior, Burea corner points mentioned in lines 3, d of Land Surveyors or by a I	05/19/15 05/20/15 do hereby state corner points mentioned in lines 1 and 2 required in the current manual of survey au of Land Management or by a decree of 4 and 5 above were in conformance with Decree of a Court of Law; established,	, 5 , 6 — 18 — 17 — 16 — 15 — 14 — 13 — 17
NOTE: Not more than 2 corn on this certificate.	ers, all in the same town and	range, may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

(C2) Quarter corner common to Sections 5 and 6. 1950 - Remonumented by Dean C. DeLaMater RLS in the original position, from an original B.T. Set 10" spike in road. 12" Hemlock N15°W 42 links, 20" S.Maple S30°W 31 links. 1977 - D.B. Babbitt RLS found the 1950 spike at record bearing and distance from the 1950 witnesses and replaced the spike with a 1" pipe and 4" alum. MDNR cap. 18" Hemlock N12°W 27.6'; 20" H.Maple S35°W 20.3'; 16" Hemlock S12°E 29.7'; 18" Hemlock N72°E 61.3'. 1995 - The undersigned found the 1977 MDNR monument in accord with the record witnesses and incorporated it into a closed traverse, controlled by static GPS observations, for a survey around Section 6. No new witnesses were made.

(9-Sec. 8) East 1/16 corner, Section 8. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C2) Found the 1977 monument pushed over by a road grader, disturbed and out of position. Remonumented the record corner position using both the record witnesses and the position as determined in 1995 by the GPS-controlled closed traverse.

(9-Sec. 8) Established the position for the corner midway and on a straight line between Quarter corner 1321.76' east and the intersection of 1/4 lines of Section 8 1321.76' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E= 7935500.528 N= 219914.801 (1/4 corner) E= 7936691.199 N= 218293.789
--

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 data Coord. Ref.=NGS PID RK0255: N= 219889.402 m. E= 7928749.670 m.

Signed by Stysher J Rysyli, al. Date 06/04/2015

Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

STEPHAN J.
SZYSZKOSKI
LAND
SURVEYOR
No.
D OF NO DESCRIPTION OF NO

FORM APPROVED BY MICHIGAN STATE BOARD OF