

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #
1. Public Land Survey	T 50N R 28W	E4 (GCDB 300540)
2. Property Controlling in Section	T 50N R 28W	E3 (GCDB 300600)
3. Miscellaneous Property in Sec.	S T R	
4. Lot No. _____, Recorded Plat	S T R	
5. Private Claims	S T R	

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 05/26/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E4) Quarter corner common to Sections 8 and 9. 1992 - Paul R. Bressette PS reestablished the corner position midway and on line between Section corners E3 and E5. Set DNR monument. 21" Sugar S29°E 34.0'; 7" Sugar S10°W 15.0'; 12" Sugar N45°W 10.6'; 14" Sugar N20°W 21.3'.

(E3) Corner common to Sections 4-5-8-9. 1992 - Paul R. Bressette PS found and accepted a 3/4" iron pipe with cedar signature tree dated to 1939 and replaced the pipe with a MI Dept. of Natural Resources monument. 3" Sugar N77°E 27.1'; 5" Sugar S50°E 16.0'; 14" Sugar S48°W 10.1'; 12" Cedar N89°W 23.7'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E4) Found the 1992 monument in good condition and at record bearing and distance from three 1992 witnesses, though I note that the bearing of the Sugar "N45°W" is recorded in the wrong quadrant and was found to be N48°E from the monument, in good condition. Also recovered was the Sugar S10°W, in good condition. The Sugar N20°W is now a dead stub. The monument is substantially at the midway position of record and I accept same as a careful and faithful reestablishment of the position of the original corner.

(E3) Found the 1992 monument in good condition and at record bearing and distance from two 1992 witnesses. The Sugar SW is a dead stub with scribing plain. The Cedar N89°W is in good condition with overgrown blazes. The 2 Sugars in the E'ly quadrants were not found and had likely been removed by road clearing. Accepted the monument as the best available evidence of the position of the original corner. The 3/4" pipe noted in the 1992 record was found adjacent to the corner monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E4) Found 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 12" Sugar N48°E 11.1' old blazes (1992 NBT) 7" Sugar S12°W 15.15' do do 10" Sugar S64°E 41.75' mrkd "1/4S NBT" 6" R.Maple S71°W 12.3' do Found sq'd post adjacent. E= 7937093.959 N= 218286.923

(E3) Found 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 13" Cedar West 24.3' scribe visible (1992 NBT) 5" Sugar S16°E 14.0' mrkd "S9 NBT" 5" Y.Birch S18°W 8.7' "S8 NBT" 8" Y.Birch N10°W 35.05' "S5 NBT" Sq'd cedar post adjacent. E= 7937100.756 N= 219086.068

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID RK0255: N= 219889.402 m. E= 7928749.670 m.

Signed by Stephan J. Szyszkoski Date 06/04/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

