LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette	. 7.8				
maiquette	_ Located In:	Corner Code #			
(County)	B		7.7		
1. Public Land Survey		29W G9 29W F11			
2. Property Controlling in Section	$\begin{array}{cccccccccccccccccccccccccccccccccccc$			*** X	
3. Miscellaneous Property in Sec.	S T R S T R S T R		1	. 100	
4. Lot No. , Red 5. Private Claims	corded Plat		Register of D	eeds Stamp & File Numb Е F G н I J	er K L M
	G9	05/01/2012	2 - 55-		
above were in conformance with	74, Michigan P.A. of 1970, the regulations and rules therefore	05/12/2012 do hereby state e corner points mentioned in lines 1 and as required in the current manual of sur	od 2 4 7 8 -	91011-	12
instructions of the United States I	Department of the Interior, Bur	reau of Land Management or by a decree	of 6 -1817-	16-15-14-	13
the rules of the Michigan Board re-established, monumented, recover	d of Land Surveyors or by a	s 3, 4 and 5 above were in conformance value and 5 above were in conformance value.	with 7 ned, 8 19 20	71 22 23	-24-
NOTE: Not more than 2 corn on this certificate.	ers, all in the same town an	nd range, may be recorded	10 30 29 11 12 31 32	33 36 35	25
			13		

- A. Description of original monument and accessories and/or subsequent restoration:
- (G9) Corner common to Sections 21-22-27-28. 1846 Established by Deputy Surveyors Hubbard and Ives. Monument not noted but was almost certainly a wood post. Maple 12" S51W 14 links, Maple 6" N75E 11 links. 1939 - Norman T. Thompson RLS ran and marked the south line of Section 21 and states about G9 "No BT old [unreadable] and corner of fence. Set hem. post. Fence running N & W." No NBTs noted in the 1939 notes.
- (F11) Quarter corner common to Sections 28 and 33. 1846 Established by Deputy Surveyors Hubbard and Ives. Set post. Hemlock 14" N26E 19 links, Hemlock 22" S29W 17 links. Found no subsequent
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (G9) The original post and accessories were not recovered. Found the nearly obliterated remains of old barbed wire fencing running N & W, unmaintained and in the ground. Reestablished the position of the 1939 post, which was not recovered, at the intersection of the fences. Found distances to adjacent corners as follows: North 5221.02' (5280' GLO), South 5255.16' (5280 GLO), West 5306.04' (5311.7' GLO), and East approx. 5286' to a found 3/4" pipe and a 4' length of 5/8" rebar in a small mound of rocks (5278.7' GLO). Accepted the fence intersection as the best available evidence of the position of the original corner and drove a monument at that position.
- (F11) The original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section corners 2648.12' east and west, being proportionate to the original record.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G9) Set 1"IDx32" I.pipe	with 4" a	alum. M	DNR o	ap.
Set measuring nail with	MDNR tag :	in the	side	of:
10" Hemlock N42E 14.35'	mrkd "S2	22 NBT"		
12" Hemlock S20E 34.7'	"S2	27 NBT"		
3" Maple S21W 4.55'	"S2	28 NBT"		
14" Hemlock N64W 38.6'	"S	21 NBT"		
Set sq'd Cedar post adja	acent.			
Bearings are magnetic.				

(F11) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 7" Sugar N12E 6.2' mrkd "1/4S NBT" do

5" Hemlock S89E 17.15' 5" Y.Birch N56W 10.7'

9" Maple N30W 24.75' Set sq'd Cedar post adjacent.

Bearings are magnetic.

Date

STEPHAN J SZYSZKOSKI LAND JRVEYOR

do

do

LAND

Surveyor's Michigan License No.

33986

07/10/2012

For the Michigan Department of Natural Resources, Forest Resources Division