MERCANDA & MILION

APR 0 6 1999

SECTION

Approved by Menominee County Land Survey Remonumentation Peer Group Under Act 345 Of

rust Gr	oab nìs ger Y	LCC 345 CE	
PA_0f1890 0n_	10/29	19	98
Terene	S- W	ani	25
	Chaleman		

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich. P. A. 1979

For corners in	CC 74, MICH.	. F.M. 1970						
MENOMINEE Located in: Corper Code #								
County) Located In: Corner Code #		}		35 81 5		(O	277	
1. Public Land Survey T 34NR 27W I-0		1			Sar Sar		RECEIVED FOR RECORD	
T_R Public Land Survey T_34NR 27W I-0	<u>I</u> :				123°	~~~		
TR				- B	ું કું. ૦ ૦	1	-71	
T p	_				13		ۇدۇ دەت	
2. Property Controlling S T P	_			30 F	200		ero Cro	
in Section S T R 3. Miscellaneous S T R				(0 t	2830.	جي		
Property in Sec. S T R		I		600	-	2		
1			D					
		L	Registe	er of D	eeds St	tamp 8	& Fîle	Numl
4. Lot No, Recorded Plat 5. Private Claims							-	
			ABC	D i	E F (Э Н	ΙJ	к
(SAME AS CORNER I-13, T35N-R27W)		2		Ţ			•	Ť
*******		3		-5-		 3 -	 2 ·	-
William Lenca , in a field survey on June 09 19 98 do	hereby etato tho	د حمامت ا		7		 	+-+	_
quirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines	f and 2 above	itunder 4 Were in	<u> </u>	— 8	j	10-	11	
nited States Department of the Interior Durant of the Interior	urvey instructions	softhe ⁵			-			-
at the corner points mentioned in lines 3. 4 and 5 at a vialing enterit or by a decree of	f a Court of Law:	and /or _c	-18	-17	16	 15	1/1-	
pard of Land Surveyors or by a Decree of a Court of Law; established, re-esta covered, found as expressed below:	e rules of the Mi blished, monum	icnigan. Tented 7			$\perp \downarrow \downarrow$			
overed, locate as expressed below:		8		-20-]	72		1
TE: Not more than 2 comers, all in the same town and range, may be record on this conflicate.	rdod	9		1	1	—22 	-23-	- 2
on this certificate.	aea				\neg		 	
		10	—30—— 	-29	28	2 ⁻ 7	26	-
		11			1 1			- 1
		1	1 }	i i	-	+-	1	
		12	-31	-32	_33	_34	35_	
Description of original monument and accessories and/or subsequent res 1847: Original Survey - Township Boundary - by H. Floyd - B.T.'s lks. All original evidence for this corner has been destroyed 1848: Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been	- Hemlock, 10 by county rost tt - B.T.'s - Bi	0" - N50°E ad improver irch, 12" - S	nents. 11 ⁰ W -	16 lks	.; Heml	lock, 1	4" -	19
 Original Survey - Township Boundary - by H. Floyd - B.T.'s lks. All original evidence for this corner has been destroyed Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been destroyed. M.D.O.T. Highway Plans show a 5/8" Iron Pin for this corner 20" - S40°W - 55.76"; P. Pole - N30°E - 18.22". (These ties It 1981: Certified Survey No. 235 by George B. Wilson shows a Cast It Description of corner evidence found and/or method applied in restoring of corner evidence found and/or method applied in restoring or corner. 	- Hemlock, 16 by county rost - B.T.'s - Bit on destroyed by r TIES: N. have been destron Monume	0" - N50°E ad improver irch, 12" - S by county row. Cor. Puttroyed.)	nents. 11°W - 1 ad impro np Stanc is corne	16 lks. overner 1 - S1: r.	.; Heml nts. 5 ⁰ E - 30	lock, 1	4" - Maple	;,
1847: Original Survey - Township Boundary - by H. Floyd - B.T.'s lks. All original evidence for this corner has been destroyed Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been 1963: M.D.O.T. Highway Plans show a 5/8" Iron Pin for this corner 20" - S40°W - 55.76"; P. Pole - N30°E - 18.22'. (These ties 1981: Certified Survey No. 235 by George B. Wilson shows a Cast 1981: Description of corner evidence found and/or method applied in restoring of We found a 1/2" diameter iron rod in a square cast iron requirement has	- Hemlock, 16 by county ros at - B.T.'s - Bi an destroyed b ar TIES: N. have been dest fron Monume or reestablishin	0" - N50°E ad improver irch, 12" - S by county ro. W. Cor. Puttroyed.) and Box at the g corner:	nents. 11°W - 1 ad impro np Stanc	16 lks. ovemen 1 - S1:	.; Heml nts. 5°E - 30	lock, 1 6.62';	4" - Maple	19
 1847: Original Survey - Township Boundary - by H. Floyd - B.T.'s lks. All original evidence for this corner has been destroyed 1848: Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been destroyed. 1963: M.D.O.T. Highway Plans show a 5/8" Iron Pin for this corner 20" - \$40°W - 55.76'; P. Pole - N30°E - 18.22'. (These ties It 1981: Certified Survey No. 235 by George B. Wilson shows a Cast It Description of corner evidence found and/or method applied in restoring of the found a 1/2" diameter iron rod in a square cast iron monument bootties shown on the 1963 Highway plats have been destroyed, however in this is the corner position which they are using. The corner falls in the been consistently used by local surveyors for at least 35 years, and is according to the second surveyors for at least 35 years. 	- Hemlock, 16 by county ros it - B.T.'s - Bi en destroyed b r TIES: N. have been dest fron Monume or reestablishin ix per Certified ewer ties by M	o" - N50°E ad improver irch, 12" - S by county ro. W. Cor. Puritroyed.) ent Box at the g corner:	nents. 11°W - : ad impro mp Stanc is corne mber 23 describe	16 lks. vement - S1: r. 5 by Ced in p	.; Heml nts. 5°E - 36 George I	B. Wil	4" - Maple Ison. 'cate th	19 The at
1847: Original Survey - Township Boundary - by H. Floyd - B.T.'s lks. All original evidence for this corner has been destroyed Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been 1963: M.D.O.T. Highway Plans show a 5/8" Iron Pin for this corne 20" - S40°W - 55.76"; P. Pole - N30°E - 18.22'. (These ties I 1981: Certified Survey No. 235 by George B. Wilson shows a Cast I Description of corner evidence found and/or method applied in restoring of We found a 1/2" diameter iron rod in a square cast iron monument botties shown on the 1963 Highway plats have been destroyed, however in this is the corner position which they are using. The corner falls in the	- Hemlock, 16 by county ros it - B.T.'s - Bi en destroyed b r TIES: N. have been dest fron Monume or reestablishin ix per Certified ewer ties by M	o" - N50°E ad improver irch, 12" - S by county ro. W. Cor. Puritroyed.) ent Box at the g corner:	nents. 11°W - : ad impro mp Stanc is corne mber 23 describe	16 lks. vement - S1: r. 5 by Ced in p	.; Heml nts. 5°E - 36 George I	B. Wil	4" - Maple Ison. 'cate th	19 The at
1847: Original Survey - Township Boundary - by H. Floyd - B.T.'s lks. All original evidence for this corner has been destroyed 1848: Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been 1963: M.D.O.T. Highway Plans show a 5/8" Iron Pin for this corner 20" - S40°W - 55.76'; P. Pole - N30°E - 18.22'. (These ties I 1981: Certified Survey No. 235 by George B. Wilson shows a Cast I Description of corner evidence found and/or method applied in restoring of the found a 1/2" diameter iron rod in a square cast iron monument botties shown on the 1963 Highway plats have been destroyed, however in this is the corner position which they are using. The corner falls in the been consistently used by local surveyors for at least 35 years, and is as	- Hemlock, 16 by county ros it - B.T.'s - Bi en destroyed b r TIES: N. have been dest fron Monume or reestablishin ix per Certified ewer ties by M	o" - N50°E ad improver irch, 12" - S by county ro. W. Cor. Puritroyed.) ent Box at the g corner:	nents. 11°W - : ad impro mp Stanc is corne mber 23 describe	16 lks. vement - S1: r. 5 by Ced in p	.; Heml nts. 5°E - 36 George I	B. Wil	4" - Maple Ison. 'cate th	19 The at
1847: Original Survey - Township Boundary - by H. Floyd - B.T.'s lks. All original evidence for this corner has been destroyed Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been 1963: M.D.O.T. Highway Plans show a 5/8" Iron Pin for this corner 20" - S40°W - 55.76'; P. Pole - N30°E - 18.22'. (These ties I 1981: Certified Survey No. 235 by George B. Wilson shows a Cast I Description of corner evidence found and/or method applied in restoring of the found a 1/2" diameter iron rod in a square cast iron monument bootties shown on the 1963 Highway plats have been destroyed, however in this is the corner position which they are using. The corner falls in the been consistently used by local surveyors for at least 35 years, and is as	- Hemlock, 16 by county ros it - B.T.'s - Bi en destroyed b r TIES: N. have been dest fron Monume or reestablishin ix per Certified ewer ties by M	o" - N50°E ad improver irch, 12" - S by county ro. W. Cor. Puritroyed.) ent Box at the g corner:	nents. 11°W - : ad impro mp Stanc is corne mber 23 describe	16 lks. vement - S1: r. 5 by Ced in p	.; Heml nts. 5°E - 36 George I	B. Willis posisition	Maple Ison. cate the	19 The at
 1847: Original Survey - Township Boundary - by H. Floyd - B.T.'s lks. All original evidence for this corner has been destroyed 1848: Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been destroyed. 1963: M.D.O.T. Highway Plans show a 5/8" Iron Pin for this corner 20" - \$40°W - 55.76'; P. Pole - N30°E - 18.22'. (These ties It 1981: Certified Survey No. 235 by George B. Wilson shows a Cast It Description of corner evidence found and/or method applied in restoring of the found a 1/2" diameter iron rod in a square cast iron monument bootties shown on the 1963 Highway plats have been destroyed, however in this is the corner position which they are using. The corner falls in the been consistently used by local surveyors for at least 35 years, and is according to the second surveyors for at least 35 years. 	- Hemlock, 16 by county ros it - B.T.'s - Bi en destroyed b r TIES: N. have been dest fron Monume or reestablishin ix per Certified ewer ties by M	o" - N50°E ad improver irch, 12" - S by county ro. W. Cor. Puritroyed.) ent Box at the g corner:	nents. 11°W - : ad impro mp Stanc is corne mber 23 describe	16 lks. vement - S1: r. 5 by Ced in p	.; Heml nts. 5°E - 36 George I	B. Williams posisition	Maple Ison. cate the tion hof the	19 The at
1847: Original Survey - Township Boundary - by H. Floyd - B.T.'s lks. All original evidence for this corner has been destroyed Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been 1963: M.D.O.T. Highway Plans show a 5/8" Iron Pin for this corner 20" - \$40°W - 55.76'; P. Pole - N30°E - 18.22'. (These ties I 1981: Certified Survey No. 235 by George B. Wilson shows a Cast I Description of corner evidence found and/or method applied in restoring of We found a 1/2" diameter iron rod in a square cast iron monument botties shown on the 1963 Highway plats have been destroyed, however in this is the corner position which they are using. The corner falls in the been consistently used by local surveyors for at least 35 years, and is acordinal corner.	- Hemlock, 16 by county roat - B.T.'s - Bit on destroyed by r TIES: N. have been desiliron Monume or reestablishing per Certified ewer ties by Me centerline of excepted as the	o" - N50°E ad improver irch, 12" - S by county row W. Cor. Purtroyed.) ent Box at the g corner: d Survey Number of Survey Num	ments. 11°W - 1 ad impro np Stanc is corner mber 23 describe Vest councile evide	16 lks. verner 1 - S1: r. 5 by Ced in proper concervers	.; Heml nts. 5°E - 36 George I	B. Willis posisition	Maple Ison. cate the	19 The at
1847: Original Survey - Township Boundary - by H. Floyd - B.T.'s lks. All original evidence for this corner has been destroyed Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been destroyed. M.D.O.T. Highway Plans show a 5/8" Iron Pin for this corner 20" - \$40°W - 55.76'; P. Pole - N30°E - 18.22'. (These ties It 1981: Certified Survey No. 235 by George B. Wilson shows a Cast It Description of corner evidence found and/or method applied in restoring of the found a 1/2" diameter iron rod in a square cast iron monument boxies shown on the 1963 Highway plats have been destroyed, however in this is the corner position which they are using. The corner falls in the seen consistently used by local surveyors for at least 35 years, and is acriginal corner.	- Hemlock, 16 by county roat - B.T.'s - Bit on destroyed by r TIES: N. have been desiliron Monume or reestablishing per Certified ewer ties by Me centerline of excepted as the	o" - N50°E ad improver irch, 12" - S by county row W. Cor. Purtroyed.) ent Box at the g corner: d Survey Number of Survey Num	ments. 11°W - 1 ad impro np Stanc is corner mber 23 describe Vest councile evide	16 lks. verner 1 - S1: r. 5 by Ced in proper concervers	.; Heml nts. 5°E - 36 George I	B. Will is posi sition	Maple ison. ison. cate thition hof the mica and veyor	19 The at
1847: Original Survey - Township Boundary - by H. Floyd - B.T.'s lks. All original evidence for this corner has been destroyed Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been 1963: M.D.O.T. Highway Plans show a 5/8" Iron Pin for this corner 20" - S40°W - 55.76'; P. Pole - N30°E - 18.22'. (These ties I 1981: Certified Survey No. 235 by George B. Wilson shows a Cast I Description of corner evidence found and/or method applied in restoring of the shown on the 1963 Highway plats have been destroyed, however in this is the corner position which they are using. The corner falls in the been consistently used by local surveyors for at least 35 years, and is accordinal corner.	- Hemlock, 16 by county roat - B.T.'s - Bit on destroyed by r TIES: N. have been desiliron Monume or reestablishing per Certified ewer ties by Net centerline of excepted as the	o" - N50°E ad improved irch, 12" - S by county row W. Cor. Put troyed.) ent Box at the g corner: d Survey Number of Survey Number of an East - Verbest available e position of	ments. 11°W - 1 ad impro np Stanc is corner mber 23 describe Vest com ole evide	16 lks. verner 1 - S1: r. 5 by Ced in proper concervers	.; Heml nts. 5°E - 36 George I	B. Williams of the state of the	Maple ison. ison. cate thation hof the many many many many many many many many	19 The at
1847: Original Survey - Township Boundary - by H. Floyd - B.T.'s lks. All original evidence for this corner has been destroyed Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been 1963: M.D.O.T. Highway Plans show a 5/8" Iron Pin for this corner 20" - \$40°W - 55.76"; P. Pole - N30°E - 18.22'. (These ties It 1981: Certified Survey No. 235 by George B. Wilson shows a Cast It Description of corner evidence found and/or method applied in restoring of the found a 1/2" diameter iron rod in a square cast iron monument booties shown on the 1963 Highway plats have been destroyed, however in this is the corner position which they are using. The corner falls in the been consistently used by local surveyors for at least 35 years, and is accordinal corner.	- Hemlock, 16 by county roat - B.T.'s - Bit on destroyed by r TIES: N. have been desiliron Monume or reestablishing per Certified ewer ties by Me centerline of excepted as the dia. iron rod in dia. iron rod in the dia.	o" - N50°E ad improved irch, 12" - S by county row W. Cor. Put troyed.) ent Box at the g corner: d Survey Number of Survey Number of an East - Verbest available e position of in Monume.	ments. 11°W - 1 ad impro np Stanc is corner mber 23 describe Vest com ole evide	16 lks. verner 1 - S1: r. 5 by Ced in proper concervers	.; Heml nts. 5°E - 36 George I	B. Williams of the state of the	Maple Ison. cate the tion h of the MARINA	19 The at
1847: Original Survey - Township Boundary - by H. Floyd - B.T.'s lks. All original evidence for this corner has been destroyed Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been 1963: M.D.O.T. Highway Plans show a 5/8" Iron Pin for this corner 20" - \$40°W - 55.76"; P. Pole - N30°E - 18.22'. (These ties It 1981: Certified Survey No. 235 by George B. Wilson shows a Cast It Description of corner evidence found and/or method applied in restoring of the shown on the 1963 Highway plats have been destroyed, however nothis is the corner position which they are using. The corner falls in the been consistently used by local surveyors for at least 35 years, and is accordinal corner.	- Hemlock, 16 by county roat - B.T.'s - Bit on destroyed by r TIES: N. have been destron Monume or reestablishing per Certified ewer ties by Me centerline of excepted as the ate locating the dia. iron rod in N25°E	o" - N50°E ad improved irch, 12" - S by county row W. Cor. Put troyed.) ent Box at the g corner: d Survey Number 1 Survey Numb	ments. 11°W - 1 ad impro np Stanc is corner mber 23 describe Vest com ole evide	16 lks. verner 1 - S1: r. 5 by Ced in proper concervers	.; Heml nts. 5°E - 36 George I	B. Williams of the state of the	Maple Ison. cate the tion h of the MARINA	19 The at
1847: Original Survey - Township Boundary - by H. Floyd - B.T.'s lks. All original evidence for this corner has been destroyed Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been 1963: M.D.O.T. Highway Plans show a 5/8" Iron Pin for this corner 20" - S40°W - 55.76"; P. Pole - N30°E - 18.22'. (These ties I 1981: Certified Survey No. 235 by George B. Wilson shows a Cast in Description of corner evidence found and/or method applied in restoring of We found a 1/2" diameter iron rod in a square cast iron monument booties shown on the 1963 Highway plats have been destroyed, however nothis is the corner position which they are using. The corner falls in the been consistently used by local surveyors for at least 35 years, and is accordinal corner. escription of monument for corner and accessories established to perpetuse 3-1/4" dia. Alum. cap stamped for corner location on existing 1/2" MDOT Tag in Power Pole N.W. Corner of House Foundation	- Hemlock, 16 by county roat - B.T.'s - Bit on destroyed by r TIES: N. have been destron Monume or reestablishing the centerline of exepted as the dia. iron rod in N25°E S23°E	o" - N50°E ad improver irch, 12" - S by county row W. Cor. Puritroyed.) and Box at the ground survey Numb.O.T. as fran East - Verbest available e position of in Monume. 23.36 feet 88.85 feet	ments. 11°W - 1 ad impro np Stanc is corner mber 23 describe Vest com ole evide	16 lks. verner 1 - S1: r. 5 by Ced in proper concervers	.; Heml nts. 5°E - 36 George I	B. Williams of the state of the	Maple Ison. cate the tion h of the MARINA	19 The at
1847: Original Survey - Township Boundary - by H. Floyd - B.T.'s lks. All original evidence for this corner has been destroyed 1848: Original Survey - Sectional Subdivision - by James H. Mullet \$46°E - 34 lks. All original evidence for this corner has been 1963: M.D.O.T. Highway Plans show a 5/8" Iron Pin for this corner 20" - \$40°W - 55.76'; P. Pole - N30°E - 18.22'. (These ties It 1981: Certified Survey No. 235 by George B. Wilson shows a Cast in Description of corner evidence found and/or method applied in restoring of the We found a 1/2" diameter iron rod in a square cast iron monument booties shown on the 1963 Highway plats have been destroyed, however in this is the corner position which they are using. The corner falls in the been consistently used by local surveyors for at least 35 years, and is accordinal corner. Set 3-1/4" dia. Alum. cap stamped for corner location on existing 1/2" MDOT Tag in Power Pole N.W. Corner of House Foundation MDOT Tag in Power Pole N.W. Corner of House Foundation MDOT Tag in Power Pole	- Hemlock, 16 by county roat - B.T.'s - Bit on destroyed by r TIES: N. have been destron Monume or reestablishing the centerline of exepted as the same locating the dia. iron rod in N25°E S23°E S75°W	o" - N50°E ad improver irch, 12" - S by county row W. Cor. Puritroyed.) and Box at the grown of Survey Numb.O.T. as fran East - Verbest available best available 23.36 feet 88.85 feet 72.86 feet	ments. 11°W - 1 ad impro imp Stance in corner imber 23 describe Vest coun ble evide the corner at Box:	16 lks. verner 1 - S1: 5 by Ced in proper of the content of the	George Dant "C" ad, The the po	B. Willis posisition	Maple Ison. cate the tion h of the MARINA	19 The at
lks. All original evidence for this corner has been destroyed Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been destroyed M.D.O.T. Highway Plans show a 5/8" Iron Pin for this corner 20" - \$40°W - 55.76'; P. Pole - N30°E - 18.22'. (These ties I 1981: Certified Survey No. 235 by George B. Wilson shows a Cast in Description of corner evidence found and/or method applied in restoring of We found a 1/2" diameter iron rod in a square cast iron monument boxies shown on the 1963 Highway plats have been destroyed, however in this is the corner position which they are using. The corner falls in the seen consistently used by local surveyors for at least 35 years, and is additional corner. **Rescription of monument for corner and accessories established to perpetuet 3-1/4" dia. Alum. cap stamped for corner location on existing 1/2" MDOT Tag in Power Pole N.W. Corner of House Foundation MDOT Tag in Power Pole 5/8" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	- Hemlock, 16 by county roat - B.T.'s - Bit on destroyed by r TIES: N. have been destron Monume or reestablishing the centerline of excepted as the same because of	o" - N50°E ad improver irch, 12" - S by county row W. Cor. Put troyed.) and Box at the g corner: d Survey Numb.O.T. as f an East - Ve best available best available e position of in Monume. 23.36 feet 88.85 feet 72.86 feet 66.61 feet	ments. 11°W - 1 ad impro imp Stance in corner imber 23 describe Vest coun ble evide the corner at Box:	16 lks. verner 1 - S1: 5 by Ced in proper of the content of the	.; Heml nts. 5°E - 36 George I	B. Willis posisition	Maple Ison. cate the tion h of the MARINA	19 The at
1847: Original Survey - Township Boundary - by H. Floyd - B.T.'s lks. All original evidence for this corner has been destroyed 1848: Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been destroyed M.D.O.T. Highway Plans show a 5/8" Iron Pin for this corner 20" - \$40°W - 55.76'; P. Pole - N30°E - 18.22'. (These ties It 1981: Certified Survey No. 235 by George B. Wilson shows a Cast in Description of corner evidence found and/or method applied in restoring of We found a 1/2" diameter iron rod in a square cast iron monument botties shown on the 1963 Highway plats have been destroyed, however in this is the corner position which they are using. The corner falls in the been consistently used by local surveyors for at least 35 years, and is accordinal corner. Description of monument for corner and accessories established to perpeture the second strong of the second strong in the second strong in Power Pole N.W. Corner of House Foundation MDOT Tag in Power Pole 5/8" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" Metal Survey Sign Post	- Hemlock, 16 by county roat - B.T.'s - Bit on destroyed by r TIES: N. have been destron Monume or reestablishing the centerline of ever ties by Me centerline of excepted as the nate locating the dia. iron rod in N25°E S23°E S75°W N27°W N20°E	o" - N50°E ad improver irch, 12" - S by county row W. Cor. Pur troyed.) ent Box at the g corner: d Survey Number 1 Survey Numb	ments. 11°W - 1° ad impro mp Stanc ins corner imber 23 describe Vest councile evide the corner at Box:	16 lks. verner 1 - S1: r. 5 by Ced in proper conce of the conce of	George Dart "C" ad. The fithe pos	B. William is position	Maple Ison. Ison. Cate the Cate the Mica MANA NICA AND VEYOR LAND TANN TA	The at as
1847: Original Survey - Township Boundary - by H. Floyd - B. T.'s lks. All original evidence for this corner has been destroyed 1848: Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been 20°E - 34 lks. All original evidence for this corner 20°E - S40°W - 55.76°; P. Pole - N30°E - 18.22°. (These ties I 1981: Certified Survey No. 235 by George B. Wilson shows a Cast I Description of corner evidence found and/or method applied in restoring of We found a 1/2" diameter iron rod in a square cast iron monument box ties shown on the 1963 Highway plats have been destroyed, however in this is the corner position which they are using. The corner falls in the been consistently used by local surveyors for at least 35 years, and is accordinal corner. Description of monument for corner and accessories established to perpetu Set 3-1/4" dia. Alum. cap stamped for corner location on existing 1/2" MDOT Tag in Power Pole N.W. Corner of House Foundation MDOT Tag in Power Pole 5/8" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" Metal Survey Sign Post NOTE: All bearings are magnetic bearings. All distances are measure.	- Hemlock, 16 by county roat - B.T.'s - Bit on destroyed by r TIES: N. have been destron Monume or reestablishing the centerline of exepted as the septed as the septed as the september of th	o" - N50°E ad improver irch, 12" - S by county row W. Cor. Put troyed.) ent Box at the g corner: d Survey Numbers an East - Verbest available best available e position of in Monume. 23.36 feet 88.85 feet 72.86 feet 66.61 feet 23.0 feet ape. Distance.	ments. 11°W - 1° ad impro mp Stance mber 23 describe Vest councile evide the commat Box: 1° S.J. ces to tre	16 lks. verner 1 - S1: r. 5 by Ced in proper conce of the conce of	George Dart "C" ad. The fithe pos	B. William is position	Maple Ison. Ison. Cate the Cate the Mica MANA NICA AND VEYOR LAND TANN TA	The at as
1847: Original Survey - Township Boundary - by H. Floyd - B.T.'s lks. All original evidence for this corner has been destroyed Original Survey - Sectional Subdivision - by James H. Mullet S46°E - 34 lks. All original evidence for this corner has been destroyed M.D.O.T. Highway Plans show a 5/8" Iron Pin for this corner 20" - \$40°W - 55.76"; P. Pole - N30°E - 18.22". (These ties It 1981: Certified Survey No. 235 by George B. Wilson shows a Cast It Description of corner evidence found and/or method applied in restoring a We found a 1/2" diameter iron rod in a square cast iron monument both ties shown on the 1963 Highway plats have been destroyed, however in this is the corner position which they are using. The corner falls in the been consistently used by local surveyors for at least 35 years, and is accordinal corner. Description of monument for corner and accessories established to perpeture the second production of monument for corner falls or at least 35 years, and is accordinal corner. Description of monument for corner and accessories established to perpeture the second production of monument for corner falls in the been consistently used by local surveyors for at least 35 years, and is accordinal corner.	- Hemlock, 16 by county roat - B.T.'s - Bit on destroyed by r TIES: N. have been destron Monume or reestablishing the centerline of exepted as the septed as the septed as the september of th	o" - N50°E ad improver irch, 12" - S by county row W. Cor. Pur troyed.) ent Box at the g corner: d Survey Number 1 Survey Numb	ments. 11°W - 1° ad impro mp Stance mber 23 describe Vest councile evide the commat Box: 1° S.J. ces to tre	16 lks. verner 1 - S1: r. 5 by Ced in proper conce of the conce of	George Dart "C" ad. The fithe pos	B. William is position	Maple Ison. Ison. Cate the Cate the Mica MANA NICA AND VEYOR LAND TANN TA	The at as