

FEB 11 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970Approved by Menominee County
Land Survey Remuneration
Fee Group Under Act 345 Of

P.A. Of 1998 On 12/30/1997

Chairman

For corners in

MENOMINEE

(County)

Located in:

Corner Code #

1. Public Land Survey

T^{35N}R^{25W}

L-05

2. Property Controlling
in Section

S

T

R

3. Miscellaneous

S

T

R

Property in Sec.

S

T

R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, William Lenca

in a field survey on Sept 22, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

97 DEC 30 PM 4:06
PAGE # 697 BK 5
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE 49888
Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5			4			3		2	1
3													
4	7			8			9			10		11	12
5													
6	18			17			16			15		14	13
7													
8	19			20			21			22		23	24
9													
10	30			29			28			27		26	25
11													
12	31			32			33			34		35	36
13													

A. Description of original monument and accessories and/or subsequent restoration:

1848: Original Survey by James H. Mullett - B.T.'s - Spruce, 6" - S39°E - 13 lks; Spruce, 4" - N50°W - 14lks. All original evidence for this corner has been destroyed by logging activities.

1970: Survey by George B. Wilson states "Found 6" Sq. cedar post - Reset Conc Mon." The corner is tied to other corners in Section 13. No B.T.'s are given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 4 inch diameter concrete monument and old squared wood post as described in George Wilson's 1970 survey. The corner position fits well with Wilson's record measurements to other corners in Section 13. This corner has been accepted and used by local surveyors for at least 27 years, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3-1/4" dia. Alum. cap stamped for corner location on existing 4" dia. Concrete Monument:

16" dia. Norway	N15°E	13.73 feet	Scr. NBT
10" dia. Hemlock (Ex. B.T.)	N73°E	11.19 feet	Scr. NBT
14" dia. White Pine (Ex. B.T.)	S17°W	17.34 feet	Scr. NBT
7" dia. Cedar (Ex. B.T.)	N80°W	12.20 feet	Scr. NBT
Metal Survey Sign Post	South	1.0 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by

William Lenca

Date

Sept 30, 1997

Surveyor's Michigan License No.

26461

