

# SURVEY & REMONUMENTATION

FEB 11 1998

Approved by Menominee County  
Land Survey Remonumentation  
Peer Group Under Act 345 of  
P.A. of 1990 On 12/18 1997  
Mc Davis, Russ  
Chairman

## SECTION

For corners in

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T35N R 25W

M-2/3 (001)

2. Property Controlling  
in Section

S

T

R

3. Miscellaneous

S

T

R

Property in Sec.

S

T

R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

SAME AS CORNER A-2/3 (002) T35N-R24W

I, William Lenca, in a field survey on June 24, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1	6	5	4	3	2	1						
2												
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

- 1847: Original Survey by James H. Mullett - B.T.'s - Cedar, 12" - N37°W - 60 lks.; Cedar, 5" - N02°W - 50 lks. All original evidence for this corner has been destroyed by ice shoves.
- 1970: Plat of Survey by George B. Wilson, RLS No. 17607, shows this corner as it relates to other corners in Section 1, T35N-R25W, and describes it as "set concrete monument". The survey also shows that Wilson re-established the original Government Meanders in order to establish this Meander Corner.
- 1992: CERTIFIED SURVEY No. 775 by William Lenca, RLS NO. 26461, shows this corner as it relates to other corners in Section 1, T35N-R25W. The map legend indicates that the corner monument is a 4" dia. concrete monument.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

The concrete monument described in Wilson's 1970 Plat of Survey and in Certified Survey No. 775 had been destroyed by high water and ice shoves. Since this corner had been re-established by retracement of original government meanders by George B. Wilson, We had accepted this corner in 1992 as a careful and faithful reestablishment of the position of the original corner. Since the corner monument has now been destroyed, we re-established a reference monument on line between the destroyed Meander Corner and the E1/4 Corner of Section 1, T35N-R25W and 66 feet North of the old Meander Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- Set 2" dia. Aluminum Pipe 30" long/3-1/4" dia. Alum cap stamped for corner location:
- |                        |       |            |          |
|------------------------|-------|------------|----------|
| 9" dia. Cedar          | N23°E | 18.37 feet | Scr. NBT |
| 8" dia. Tamarack       | S86°E | 8.99 feet  | Scr. NBT |
| 8" dia. Tamarack       | S66°W | 48.37 feet | Scr. NBT |
| Metal Survey Sign Post | N73°W | 1.15 feet  |          |

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca  
Surveyor's Michigan License No. 26461

Date July 18, 1997

