STATE OF MICHIGAN COUNTY OF OCEANA RECEIVED FOR RECORD

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 3 DEC 1999 2:12:08 PM For corners in **Oceana** Located In: JOSEPH E. NERTEN Corner Code # (County) REGISTER OF DEEDS T 15NR 18W 1. Public Land Survey H - 7100941 R T R 2. Property Controlling R in Section R 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. . Recorded Plat 5. Private Claims J. Randolph Hepworthin a field survey on October 149 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or 5 6 that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, 7 recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded 9 on this certificate. 10 1: A. Description of original monument and accessories and/or subsequent restoration: H-7 1/4 CORNER COMMON TO SECTIONS 15 AND 22 T15N, R18W **GOLDEN TOWNSHIP** J. Mullett 1838 SET POST 8" Beech N70°E (11 lks) 7.3' 6" Beech S72°W (13 lks) 8.6' Book A, Pg. 198, EM Hyde, 1888; " Set a gray stone 4X7X15 inches in the angle of the fence." Book A, Pg. 408, H.A.Grant, 1895; No witnesses cited. Oceana County Remonumentation LCRC #100256, K. Ross #17634, 1/21/77, Set 1" Pipe at Fence corner Peer Group Reviewed & Approved 1) 12" Oak 2) 30" Tw Maple S30°E 8.76 11-11-99 23.48 N 8" R Pine S80°E 20.80 124 4) Cor fen post J. Randolph Hepworth Unrecorded Survey, JR Hepworth #26457, 6/24/85 Replaced from Witness-Set 1/2" Iron Oceana County Surveyor 2) 30" Tw Maple 23.48 8" R Pine 3) \$80°E 20.80 12" R Oak 5) \$70°F 29.09 10" R Oak S85°E 31 42 8" Cedar Post w 2.63 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. I found a JRH 1/2" from at position of the JRH 1985 witnesses. All JRH witnesses are standing and measure OK, Except the 8" Cedar Post had been moved to be beside the found Iron. I set this Iron in 1985 at the position of Ross, LCRC 100256, because it had been destroyed by land clearing operations. Ross stated he set the pipe at a fence corner post. I found no stone, but this area has been much disturbed since 1888. Corner is at the transported that the corner post is at the transported by the pipe at a fence corner post. intersection of old occupation lines N-S&E. No occupation is visible to the west across an open field. I accept the JRH 1/2" Iron as the best available evidence of the position of the original corner. No evidence is known to me that would lead me to believe the corner should be at another location. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 5) 60d spk **NE Face** 16" Oak 129°az 29.32 **EDM** 6) 60d spk S Face 14" Oak 100°az 31.34 **EDM** E of MICHICA NE Face 60d spk 4" Oak 338°az tape 60d spk N Face cedar post East 2.40 tape Date November 30 990 LAND
990 LAND
990 LAND
NO.
26457
FORM APPROVED BY MICHIGAN STATE BOARD OF ROPESSONAL SURVEYOR J. RANDOLPH Signed by 26457 Surveyor's Michigan License No.

SIGNAL BURVEY VISED MAY REVISED JAN., 1983 REVISED OCT., 1995