## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

on this certificate.

Ontonagon (County)	Located In:	Corner Code #	
1. Public Land Survey	T R T		
2. Property Controlling in Section	S 32 T 51N R 37W S 32 T 51N R 37W S T R	D12 5	
3. Miscellaneous Property in Sec.	S T R S T R		N. Serial Control of the Control of
4. Lot No. , Re 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number
	D12 04/0	8/2010	2 -6-+-6-+-6-+-3-+-2-+-1-
I, Stephan J. Szyszkoski, in a field survey on 5 04/08/2010 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6			5 6 18 17 16 15 14 13
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, B re-established, monumented, recovered found as expressed below:			7

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

(D12) Center of Section 32. 1979 - Established by K.L.Sackett RLS at the intersection of 1/4 lines. A 2006 survey by J.Domitrovich PS shows that the 1979 position for 1/4 corner C12 was not correct, rendering the 1979 position of D12 erroneous. Ca. 1907-1910 mining compnay survey shows this corner to have been monumented at the intersection of straight lines connecting opposite 1/4 corners. The mining company record position for C12 agrees with that monumented by Mr. Domitrovich.

(5-Sec. 32) North 1/16 corner, Section 32. Not established in the original survey. Found no record that this corner was monumented in the ca. 1907-1910 mining company survey of Sections 31, 32, and

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (D12) Established the corner at the intersection of straight lines connecting opposite 1/4 corners. Found no evidence of the 1907-1910 mining company monument. Found the 1979 monument N41W 40.7' distant and removed it.
- (5-Sec. 32) Established the corner midway and on a straight line between Center of Section 32 1344.50' south and Quarter corner D11 1344.50' north.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D12) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. (5) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: Set measuring nail with MDNR tag in the side of: 4" Elm N10E 25.3' mrkd "C1/4 BT" 6" Maple North 14.2' mrkd "1/16S BT" 9" Hemlock S40E 47.3 do 12" Sugar S81E 25.9' do 4" Sugar S69W 21.8' do 7" Sugar S20E 30.6' do 12" Hemlock N50W 25.0' do 9" Maple S55W 1.4' Set cedar post adjacent. Bearings magnetic. Set cedar post adjacent. Bearings magnetic.

Signed by Surveyor's Michigan License No.

09/07/2010

SZYSZKOSK

LAND

STEPHAN J

For the Michigan Department of Natural Resources and Environment, Forest Management

16397

16396

FORM APPROVED BY MICHIGAN STATE BOARD

ised Jan., 1983

Rervised Oct., 1995