## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

on this certificate.

Ontonagon (County)	Located In: Corner Code #		A.	
1. Public Land Survey	T 51N R 37W	M12 (GCDB 700140)		
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	S 36 T 51N R 37W S T R S T R S T R S T R	12 (GCDB 640120)		
4. Lot No. , Re 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number  A B C D E F G H I J K L 1	
above were in conformance with instructions of the United States a Court of Law and /or that the	74, Michigan P.A. of 1970, the corne regulations and rules therefore as requipers as the properties of the Interior, Bureau of corner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree	uired in the current manual of surver Land Management or by a decree or and 5 above were in conformance with	by 5	

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

(12-Sec. 36) Center-South 1/16 corner, Section 36. Not previously monumented.

(M12) Quarter corner common to Sec. 36 T51N-R37W and Sec. 31 T51N-R36W. 1854 - Established by Wm.A.Burt Deputy Surveyor 33.18 ch. North of MC on north side of lake and 40.00 ch. South of Section corner. Set post. Birch 14" S65°W 36 links, Maple 16" N60°W 41 links. 1957 - MSHD highway plans show 1.5" iron pipe at corner and witnesses: S52°E 12" Maple 13.30'; N55°W 5" Maple 6.88'; S74°W 7" Maple 21.22'. 1990 - R.W.Crampton RLS found 1.5" iron pipe and set witness nails with tags in: 5" Cherry N12°W 31.44'; 5" Maple N89°E 30.91'; 22" Hemlock S88°E 32.35'; 5" Maple N84°W 29.58'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12-Sec. 36) Established the position for the corner midway and on a straight line between Quarter corner 1350.47' south and the Center of Section 36 1350.47' north.

(M12) The original post and accessories were not recovered. Found a 1.5" ID iron pipe, top bent over but below-ground portion still plumb and firm. The 1957 NBT Maple S74°W 21.22' was found at record bearing and distance, now a very low cut stump. The 1957 NBT Maple S52°E 13.30' is a rotted stump. But for the Hemlock S88°E 32.35' which was not found, the 1990 witnesses are in good condition and at record bearing and distance. The pipe is 40.068 chains S0°00'22"W (true bearing) from the monumented Section corner M11. I accepted the pipe as the best available evidence of the position of the original corner. Replaced it with a new monument, described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

		_ ,		
(12) Set 1"IDx28" I.pipe with 2" al Set measuring nail with MDNR tag ir 7" Oak N08°E 7.3' mr} 5" Oak N85°E 1.9' 5" Oak S20°E 5.55' 4" R.Pine N26°W 26.5' Set sq'd Cedar post adjacent. E= 7851614.959 N= 222456.983	lum. MDNR cap. n the side of: kd "1/16S BT" do do do	(M12) Set l"IDx28" I.pip at the position of a for Set measuring nail with 5" Sugar N31°E 11.45' 5" Y.Birch N79°E 8.55' 4" Y.Birch S60°W 3.2' 4" Sugar N40°W 20.0' Set sq'd Cedar post adja E= 7852423.083 N= 222846	und 1.5" ID iron pipe MDNR tag in the side mrkd "1/4S NBT" do do do do	

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Coord. Ref.=NGS PID RL0607: N= 222113.185 m. E= 7850163.394 m.	Datum)	
signed by Stephen Smaller Date 06/30/2014	* STEPHAN J.	
For the Michigan Department of Natural Resources, Forest Resources Division	LAND SURVEYOR	

FORM APPROVED BY MICHIGAN STATE BI

AND S No. 3 Seed Jan., 1983 Revised Oct., 1995