

MAR 02 2001

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Ontonagon County Located in: Corner Code #

1. Public Land Survey T51N R38W H-9  
T R  
T R  
T R

2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R

4. Lot No. , Recorded Plat

5. Private Claims

JUDITH D. ROEHM 1P  
Ontonagon County  
Page 1 of 1 LC 5/365  
JEM Date 01/03/2001 Time 14:37:57  
RECORDING FEE: 9.00

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4			3			2	1
3													
4	7		8			9			10			11	12
5													
6	18		17			16			15			14	13
7													
8	19		20			21			22			23	24
9													
10	30		29			28			27			26	25
11													
12	31		32			33			34			35	36
13													

I, Joseph C. Domitrovich, in a field survey on December 13, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(H-9) ¼ Corner Common to Sections 22 and 27, T51N, R38W

1846- H. and S.W. Higgins set a ¼ post.  
10" Sugar N 35°W 18 links  
12" Sugar S 50°E 30 links

I found no recored of subsequent restoration but Milton Eva RLS 1767 and William A. Waara (Copper Range Forester) were doing retracement work in this area in the 1930's to 1950's.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of the original corner or accessories. I found a 2 ¼ " bent iron pipe at the corner position. The position of this pipe works well with 1/16 corner pipe and fence corner to the east. Distance East to the Section corner is very short but this is not inconsistent with the type of work done by the original surveyors in this and other townships. I have accepted the position of the iron pipe as the best representation of the position of the original ¼ corner and have placed a county monument at it.

Research on file with County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 2 ½" x 30" aluminum pipe with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T51N, R38W; ¼; S. 22, S.27; 2000; P.S. 37273. Corner falls 22' North of an East-West electric fence.

Ties:

12" Basswood	N 38°W	38.88'
5" Poplar	North	2.83'
8" Hard Maple	N 33°E	30.43'
Steel Sign Rail	South	0.52' (to face)
NE Cor. S. 27	N 89°11'19"E	2382.65'
NW Cor. S. 27	S 85°40'17"W	2621.35'

PEER GROUP APPROVED  
*Earl W. Applekamp*  
COUNTY REGISTER  
12-19-00



NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted. Bearings shown between corners are on assumed basis, for reference only.

Signed by *J.C. Domitrovich*

Date 12/19/00

Surveyor's Michigan License No. 37273