LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon (County)	Located In:	Corner Code #	48		
1. Public Land Survey	T R		1 20		100 Es
	r R		1		
2. Property Controlling in Section	S 16 T 53N R 37W S 16 T 53N R 37W	15 11			
3. Miscellaneous	S T R	*)			
Property in Sec.	STR	-			
4. Lot No. , Red 5. Private Claims	corded Plat		Register of Deed	s Stamp & File Num	K L M
	15 08	3/28/2012	2 - 5 5	╺╽╾┼╾┆╌┼╴┆	
ı, Stephan J. Szyszkoski , i	n a field survey on 11 08	3/23/2012 do hereby state	3		
	74, Michigan P.A. of 1970, the corner		₂ 4	- 9	l
above were in conformance with	regulations and rules therefore as requ	aired in the current manual of survey	y 5	++++	
instructions of the United States	Department of the Interior, Bureau of	Land Management or by a decree o	(6 19 17	-161514	1/3-
the rules of the Michigan Boar	corner points mentioned in lines 3, 4 ard d of Land Surveyors or by a Decre	nd 5 above were in conformance with	7		
re-established, monumented, recov	ered, found as expressed below:	ee or a court or Law; established	9 19 20	-212223	24
NOTE: Not more than 2 corr	name all to the court tour		10 30 29	-26 -27 -20	525
on this certificate.	ners, all in the same town and rang	ge, may be recorded	11		
on una certificate,			12 31 32	-3/3 -34 -3/5	36-
A. Danadation of a 1.1.1		10	13		
A. Description of original m	nonument and accessories and/o	r subsequent restoration:			*

corner position midway and on line between Section and Quarter corners. Set 1"IDx36" Iron pipe with 4" alum. cap. 10" Y.Birch S10E 6.1', 4" Y.Birch West 10.0', 5" Y.Birch N45E 3.2'.

(11-Sec. 16) Southwest 1/16 corner, Section 16. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(15-Sec. 16) Found the 1979 monument in good condition and at record bearing and distance from the 1979 accessories but S55E 5.5' distant from the midway position of record. I did not accept the 1979 position and I established the position for the corner midway and on the Section line between Section corner 1343.79' west and Quarter corner 1343.79' east. Removed the 1979 monument.

(15-Sec. 16) West 1/16 corner between Sections 16 and 21. 1979 - K.L.Sackett RLS monumented the

(11-Sec. 16) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(15) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 6" Y.Birch S82E 6.8' mrkd "1/16S BT" 1979 BT 15" Y.Birch S29E 11.25' do do 5" Y.Birch S67W 6.5' do do 13" Maple N04E 17.85' do Set sq'd cedar post adjacent. Bearings are magnetic.

(11) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 5" Maple N07W 19.65' mrkd "1/16S BT"

7" Y.Birch S80E 14.0' 5" Y.Birch S54W 13.15'

6" Y.Birch N55W 16.0' do

Set sq'd cedar post adjacent.

Bearings are magnetic.

33986 For the Michigan Department of Natural Resources, Forest Resources Division

STEPHAN J SZYSZKOSKI LAND WRVEYOR No. 33986

do

60 ESSIDNADSURVE

16971

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD

d May 14, 1975 Revised Jan., 1983

16966

IAN, 28, 1971