## LAND CORNER RECORDATION CERTIFICATE

94 AUG 12 PM 2: 38

Filing Requirement of Act 74, Mich. P.A. 1970

				- 4	•
.IBER	NO.	1	PAGE		465

For corners in

Sanilac Located in: Corner Code ## 10N <sub>R</sub> 15E 1. Public Land Survey R

T

Т

R

REGISTER OF DEEDS SANILAC CO. MICHIGAN

2. Property Controlling

Property in Sec.

\_ R \_ Т \_\_ R \_\_ in Section Т \_\_ T \_\_\_\_ R \_ Miscellaneous R

Register of Deeds Stamp & File Number

\_\_ , Recorded Plat \_ Lot No.

Private Claims \_

John A Milletics, in a field survey on July 12 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: M - 6 Found 1/2" iron bar in gravel road, per survey dated 8-05-80 Sanilac Land Surveying

M-7 Found 5/8 Iron Bar in paved surface, per survey dated 8-05-80Sanilac Land Surveying

Approved Peer Board Meeting Aug. 9, 1994-

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M - 6

E 1/4 Corner Section 13 T10N-R15E Found 1/2" Iron bar

M - 7

SE Corner Section 13 T10N-R15E Found 5/8" Iron Bar

SURVEY & REMONUMENTATION

SEP 07 1994

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E 1/4 Cor Section 13 T10N-R15E

1/2" Iron Bar

S30°E 103.8 to a nail W side of a 24"Maple

N30°E 112.5 to a nail SE side of a Tele Pole N40°W 40.8 to a nail NE side of a Guard Rail Post

East 33.00 to a 1/2" Iron

South 2639.44 to the SE Cor of Sec. 13

M - 7

SE Cor Section 13 T10N-R15E

Monu Box

N45°E 38.7 to a nail SE side of a Fence Post

10

S45°W 87.2 to a nail NW side of a Anchor Pole

West 2643.0 to the S 1/4 Cor Section 13

Surveyor's Michigan License No. ....

25859

Date

REVISED MAY 14, 1975

REVISED JAN., 1983