

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft	Located In:	Corner Code #
(County)		
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 20 T 43N R 14W	8
	S 20 T 43N R 14W	4
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 06/10/13 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(8) West 1/16 corner, Section 20. 1978 - Established by D.B.Babbitt RLS midway and on line between W1/4 corner and Center of Section 20. Set 1"ID I. pipe with 4" alum. MDNR cap. 6" J.Pine N55°E 8.65', 6" J.Pine S44°E 20.6', 5" Spruce S35°W 14.15', 6" J.Pine N67°W 8.8'.

(4) Northwest 1/16 corner, Section 20. 1978 - Established by D.B.Babbitt RLS at the intersection of 1/16 lines. Set 1"ID I.pipe with 4" alum. MDNR cap. 4" Tamarack S10°E 32.7', 5" Tamarack N44°E 66.8', 6" Spruce N80°W 23.0', 7" Spruce S10°W 7.6'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8) Found the 1978 monument in good condition and at record bearing and distance from the 1978 witnesses, now all dead. Checked the position of the monument with respect to corners at C8 and #4, Section 20 and found it to be in accord with the record of the 1978 survey. Accepted the monument as a careful and faithful establishment of the position of the corner.

(4) Found the 1978 monument in good condition and at record bearing and distance from the 1978 witnesses found as follows: Tam. SE in good condition, Tam NE standing dead, Spruce NW dead and down, Spruce SW dead and down. Checked the position of the monument with respect to corners at C8 and #8, Section 20 and found it to be in accord with the record of the 1978 survey. Accepted the monument as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Found 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
 7" J.Pine S16°W 24.75' mrkd "W1/16 BT"
 4" B.Spruce S76°W 27.8' do
 4" J.Pine N38°E 15.35' do
 5" J.Pine S24°E 40.6' do
 E= 8070409.924 N= 147579.348

(4) Found 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
 5" Tamarack S05°E 33.0' (1978 BT)
 5" Tamarack S54°E 12.9' mrkd "NW1/16 BT"
 5" B.Spruce S62°W 34.5' do
 6" Tamarack N23°E 18.25' do
 E= 8070401.566 N= 147983.038

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum) Date
 Coord. Ref.=NGS PID DL6163: N= 131822.939 m. E= 8059239.498 m.

Signed by Stephan J. Szyszkoski
 Surveyor's Michigan License No. 33986

Date 06/12/2013

For the Michigan Department of Natural Resources, Forest Resources Division

