## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft	_ Located In:	Corner Code #							
(County)			81						
1. Public Land Survey	TR	III.				20			
	T		.						
2. Property Controlling in Section	S 17 T 43N R 16 S T R S T R	11 11				C.			
3. Miscellaneous Property in Sec.	S T R				ų.				
4 Lot No. Dog	and of Disk		L	Regist	er of De	eds Stam	p & File	Number	
4. Lot No. , Rec 5. Private Claims	corded Plat		. A	Billo	D 1	E F G	н т	i ay k	T. M
J. Private Claims				1135	12				
				ì			_ }_	-2-	-1-1
ı, Stephan J. Szyszkoski , ir	a field survey on 10/	25/2011 do here	by state						
that under requirements of P.A.	74, Michigan P.A. of 1970, the o	corner points mentioned in line	s 1 and 2	=7	8	<b>├</b> -१-┤	-10	11	-12-
above were in conformance with a					-	╂╾╂╼┦	1-1	- 1	╼╼╂═╌┨
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of				-18	17	16	-15	-14-	-13-
a Court of Law and /or that the c					-		_	6 (i)	
the rules of the Michigan Board		Decree of a Court of Law; e	stablished, a	-19	-50-	23	22	_23_	-24-
re-established, monumented, recove	ered, found as expressed below:		9 _	-	<b></b>	9			1 5
NOTE: Not more than 2 corn	ers, all in the same town and	range, may be recorded	10-	-30	29	28	_27_	-26-	_25
on this certificate.			12	-31	-32-	33	-34-	_35	36
			13				111		
A. Description of original m	onument and accessories an	d/or subsequent restoration	on:						

(11-Sec. 17) Southwest 1/16 corner, Section 17. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(11-Sec. 17) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners. The position for the corner falls in Smith Creek and cannot be monumented. Established a WITNESS CORNER on the South 1/16 line 25.00' east of the corner position. Note: The monuments for Government corners C6, E6, and D7, placed in 2007 for Schoolcraft County Remonumentation, were discovered to have been placed in erroneous positions. The position for the 1/16 corner herein described was calculated using the proper positions for these corners, based upon the method of reestablishment described in the certificates of record, L5 P453 and L5 P397. Schoolcraft County Remonumentation has expressed their intention to correct the positions of the monuments for C6, E6, and D7.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(11) Set 1"IDx36" I.pipe with 4" alum. MDNR cap for a WITNESS CORNER 25.00' east of the corner position and on the South 1/16 line. Set measuring nail with MDNR tag in the side of: 8" Maple S28W 1.5' mrkd "WC BT" 9" Balsam S07E 10.35' do 10" Maple N01W 19.2' do 8" Maple N80E 14.2' do River bank is 7.5' west.

Bearings are magnetic.



Date

02/27/2012

Surveyor's Michigan License No.

Signed by

rse No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division