## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Schoolcraft Co.

3 Corners.

	FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	1
	1. PUBLIC LAND SURVEY	т. <u>44</u> х., к. <u>13</u> ж.	G-13, F-13, E-13	
	2. PROPERTY CONTROLL- ING IN SECTION—	,T		
	3. MISCELLANEOUS PROPERTY IN SECTION	,T		
	4. LOT NO, RECORDED PLAT			
	5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
	I, David B. Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 8-4 & 10-11 & 11-10, 1982, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on, 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
<b>C</b> -1	A. Description of original monument and accessories and/or subsequent restoration:  Sec. Cor., Southeast sec. 33. Wood Post, OBT'S Eeech 10", N62°E, 32 lks. & Sugar 6", N45°W, 15 lks. M.S.D.H.D. 1½" Shaft. 12" Elm, S65°W, 41.84' & 12" Maple, S45°W, 49.80 & 10" Maple, N60°W, 73.25'.			
F-1	South 1/4 cor. of sec. 33. Wood Post, OLT'S Sugar 14", N32°E, 40 lks. & Ironwood 6", N25°W 18 lks.			
€-1	Southwest sec. cor. of sec. 33. Wood Post, OET'S Hemlock 20", N20°E, 18 lks. & Hemlock 14", N33°W, 40 lks.			
<b>G</b> -1]	B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  Found 1½" Iron bar buried in E-W dirt road. Set 5/8" re-rod and plastic RLS cap over it.  M.S.H.D. NETS would fall in the clear vision area of road intersection.			
F-13	Set M.P.O.L. between the S.E. and S.W. sec. corners of sec. 33.			
€-1)	Set by single proportionate measurement between the $S^1_{\overline{\tau}}$ cor. of sec. 32 and the SE sec. cor. of sec. 33.			
<b>G</b> -13	C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  5/8" re-rod W/R.L.S. cap. New Bearings: 12" R. Maple, N71°W, 137.4' & 12" H. Maple, S78°W, 135.0' & 16" H. Maple, N85°E, 113.6' & Center line M-77, East, 54.35' and corner lies in center of East - West road.			
F-13	1" pipe W/RLS cap buried. New Eearings: 10" Ironwood, N51°E, 28.4' & 8" R. Maple, N52°W, 30.7' & 4" R. Maple, S42°W, 27.9' & 8" R. Maple, S20°W, 27.0'.			
<b>E</b> -13	3 1" pipe W/RLS cap bur N5°E, 31.5' & 12" He in road.	ied. New Eearings: mlock, S44 <sup>0</sup> W, 42.7	14" Hemlock, N56°E, & 10" Cedar, S52°E,	75.7' & 14" Hemlock, 24.5'. Corner lies
	SIGNED BY David B. Babbitt DATE 1-25-83			
	SURVEYOR'S MICHIGAN REC	SISTRATION NO. 21558		(SRAL)
	FOR STATE AND UNITED ST	ATES AGENCIES:		