

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T 44N R 16W	I11
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 03/05/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner common to Sections 26-27-34-35. 1964 - Arthur O. Enger RLS and Frank J. Bray RLS
reestablished the corner position by proportionate measurement. Set 1"ID x 4' iron pipe. 7" J.Pine
S74E 08 links, 7" J.Pine S41W 18 links, 6" J.Pine N34W 40 links. 1992 - the undersigned recovered
the 1964 monument in good condition and found the true bearing and distance I11 to H11 = N89°53'36"W
2659.55' by traverse and solar observation.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found the 1964 monument in good condition, at record bearing and distance from the stump remains of
the NBT J.Pine S74E 08 links. If the remains of the other two NBTs still exist, they were not
observed above the snow. Found the true bearing and distance to H11 to be N89°53'55"W 2659.41' by
GPS observations. Accepted the monument as a careful and faithful reestablishment of the position
of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 1"ID iron pipe.
Set measuring nail with MDNR tag in the side of:
6" Maple S89°E 50.65' mrkd "S35 NBT"
4" J.Pine N26°W 46.9' "S27 NBT"
15" R.Pine S61°E 60.0' "S35 NBT"
4" R.Pine S24°E 16.25' "S35 NBT"
E=8055430.908 N=154651.800



Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Signed by Stephan J. Szyszkoski Date 03/20/2013
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995