## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft	Located In:	Corner Code #		
(County)	- "			
1. Public Land Survey	T R			
2. Property Controlling in Section	S 33 T 46N R 13W S 33 T 46N R 13W S T R	•		
3. Miscellaneous Property in Sec.	S T R		Register of Deeds Stamp & File N	Number
4. Lot No. , Rec 5. Private Claims	corded Plat	<u> </u>	ABCDEFGHI	J K 1, M
J. Fired Caming	1 0	98/31/3011	a - 5 - 5 -	
above were in conformance with instructions of the United States I a Court of Law and /or that the co	74, Michigan P.A. of 1970, the corregulations and rules therefore as re- Department of the Interior, Bureau corner points mentioned in lines 3, 4	08/30/3011 do hereby state the points mentioned in lines 1 and 2 quired in the current manual of survey of Land Management or by a decree of and 5 above were in conformance with	by 5 of 6 18 17 16 15	-1112-
re-established, monumented, recover	or Land Surveyors or by a Decered, found as expressed below:	ree of a Court of Law; established	9 20 21 22	_2324
NOTE: Not more than 2 corn on this certificate.	ers, all in the same town and rar	age, may be recorded	10 30 29 28 27 11 12 31 32 33 34	-26 -25 -35 -36

A. Description of original monument and accessories and/or subsequent restoration:

(1-Sec. 33) West 1/16 corner between Sections 28 and 33. Found no record of prior monumentation.

(4-Sec. 33) Northwest 1/16 corner, Section 33. 2002 - Monumented by Robert Goodreau PS 43053 and shown on his U.P. Engineering and Architects, Inc. survey drawing prepared for Seney Township (File No. S05-22405). No witnesses noted.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1-Sec. 33) Established the position for the corner midway and on the Section line between Section corner E11 1327.14' west and Quarter corner F11 1327.14' east. The position for the corner falls 2.3' north of the south edge of the pavement of highway M-28.

(4-Sec. 33) Established the corner at the intersection of straight lines connecting opposite 1/16 corners. 1/16 corners #1,#3, and #8 are monumented by the undersigned. 1/16 corner #5 was calculated being midway between F11 and F12. I did not accept Mr. Goodreau's position for 1/16 #4, it having been determined by his relying upon an erroneous position for 1/16 corner #8. I found Mr. Goodreau's 2002 monument, a 5/8" capped rebar, N87 deg. 55'22"E, 9.50' distant (MCS83 grid bearing).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(1) Set 5/8"x24" rebar with plastic MDNR cap. Set measuring nail with MDNR tag in:
9" J.Pine N30E 101.16' mrkd "Wl/16 BT"
Power pole S47W 16.4'
sign post S01W 10.55'
The striped c/l of M-28 is North 20.75'
Bearings are magnetic.

(4) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 7" Tamarack S60W 3.85' mrkd "NW1/16 BT" 14" W.Pine N22E 24.95' do 7" Tamarack S39E 19.6' do 8" Tamarack N22W 37.8' do 5/8" capped rebar East 9.50'

DISTILLE DY		1-4	<i>rec</i>
Surveyor's	Michigan	License	No.

33986

12/28/2011

Bearings are magnetic.

Date

For the Michigan Department of Natural Resources, Forest Management Division

47491

FORM APPROVED BY MICHIGAN STATE BOARD CA

A N D Sevised July 14, 1975 Rervised Jan., 1983 Rervised Oct., 1995

OF MICH

STEPHAN J

SZYSZKOSK

LAND

SURVEYOR