Van Buren County Remonumentation Programme 20 2 47 PM 196 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Quarter Corner 21,22 For corners in Arlington Township Corner Code # Van Buren Located In: (County) T2S R15W G8 1. Public Land Survey 2. Property Controlling Ratified by Peer Group to In Section Liber 4 Page 489 cerdance with P.A. 345 of 1990 3. Miscellaneous R Van Buren County Surveyor Property in Sec. Register of Deeds Stamp & File Number Data 12/20/96 D. R , Recorded Plat Lot No. 5. Private Claims , 19.93 do hereby state that under 5/28 Gary C. Bilow _, in a field survey on _ requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Post established by U.S. Deputy Surveyor G. Harrison in 1830 - accessories: Tamarack 4 N69E 50 links and Tamarack 3 S77-1/2W 25 links. County Surveyor A.J. Pierce recorded in 1870 in Volume 4 Page 33 "Stake - one (1) witness standing with stump of others remaining - set Guard 9 links East." County Surveyor T.A. Smith recorded in 1930 in his field notes "Iron Pipe set - no accessories given - method used: measured 1319.0' to East/West fences then doubled and set Iron Pipe 7' East of centerline of North/South road on East/West 1/4 line." J. Hunt (PS #23513) recorded on a Act 74 record in Liber 2 Page 493 "Found 1" Iron Pipe - accessories: N50W 66.2', Nail & Washer in South face triple Oak, East 7' Street sign, S45W 83.7' Nail in East face triple Oak, West 6' centerline North/South road." Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 1" Iron Pipe and two (2) of Hunts accessories. Distances to adjacent corners was reasonable and consistent. Accepted this Iron Pipe as the best evidence of the original GLO post. THIS GOVERNMENT MONUMENT WAS RESTORED WITH THE APPOVAL OF THE VAN BUREN COUNTY REMONUMENTAION PEER GROUP OF SURVEYORS AT A MEETING HELD SEPTEMBER 25, 1996, AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER. Description of monument for corner and accessories established to perpetuate locating the position of the corner Replaced 1" Iron Pipe with Harrison Monument on 12/19/96 OF MICHIG Spike & tag in 8" Maple **S30°W** GARY C. centerline 52nd street West BILCW 10.9' Street Sign post N78°E ROPESSIONAL

PAGE 18

51.39 spike & tag in 12" Willow

49.5' Stop Sign post

S81°W

S30°E

December 19,1996

BUHYEYON

Ν'n.

23653

OFESSION