

SURVEY &  
REMONUMENTATION

COPY

RECORDED  
WASHTENAW COUNTY, MI

MAY - 1 1995

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

FEB 1 8 50 AM '95

For corners in

COMMISSION

WASHTENAW

(County)

Located In:

Corner Code #

1. Public Land Survey

T 4 S R 4 E

K-9

2. Property controlling  
in Section

S

T

R

3. Miscellaneous

S

T

R

Property in Sec.

S

T

R

4. Lot No. , Recorded Plat

5. Private Claims

PEGGY M. HAINES  
COUNTY CLERK/REGISTER

-COPY-

LIDER

1 PAGE 346 RM

COPY

Register of Deeds Stamp & File Number

I, Paul V. Schwimmer, in a field survey on October 21, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate

A. Description of original monument and accessories and/or subsequent restoration:

Wood post GLO August 27, 1819

- (1) Lynn 12" bears N 88° W 20 links  
(2) Hickory 20" bears S 15° E 29 links

Found Railroad spike

No witnesses remaining

Subsequent survey indicates this point is same as previously used. Replaced Railroad spike w/ 1" X 24" iron pipe.

(5) Hickory 12" S 49° W 48.43' to nail

(6) Hickory 15" S 61° W 59.65' to nail

(7) Maple 24" S 82° E 231.31' to nail

(8) Oak 24" North 209.75' to nail

No description of corner

(3) W. Oak 24" N 32° E 35 links

(4) B. Walnut S 26° W 46 links

Surveyor named Curtis

No date

Norman N. Fahrner LS 17620

LCRC L1 P519

11/24/71

B. Description of corner evidence and/or method applied in restoring or reestablishing corner:

Found 3/4" iron pipe, 6" below road surface, from remaining witnesses.

Set offsets and removed iron pipe to check for additional corner evidence. Found 3/4" x 18" iron pipe 24" below road surface. Removed this iron pipe as well. Found no further corner evidence.

Reset iron pipes at same depths using offsets.

(5) Hickory 15" S 49° W 48.41' to nail on N. side

(6) Hickory 18" S 61° W 59.65' to nail on N. side

(8) Oak 30" North 209.75' to nail on E. side

(11) 6" X 8" Wood fence post N 20° E 26.26' to PK nail on W. side

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Removed existing iron pipes and set 1" x 24" iron pipe w/ remonumentation cap 6" below road surface.

Set additional accessory

12) Shagbark Hickory 18" N 83° W 225.24' to PK nail on N. side

I believe this point should be accepted as the best available evidence of the original corner.

Signed by Paul V. Schwimmer

Date

12/29/94

Surveyor's Michigan License No.

24618

APPROVED

DATE 12-12-94

CO. REP. PA

