LAND	CORNER RECORDATION CERTIFICAT	ŕÌ
Filing	Requirement of Act 74 Mich PA 197	

For corners in:		requirement of Act 14, IM		
<u>Marquette</u> (County)	Located In:	Corner Code #		
1. Public Land Survey	T <u>42N</u> R <u>26W</u> T R T R	I-04		
2. Property Controlling in Section 3. Miscellaneous Property in Sec. 4. Lot No.	S T R S T R S T R S T R Recorded Plat			

5. Private Claims

I, <u>Thaddeus A. Goodwin</u>, in a field survey on <u>August 19th, 2016</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: One Quarter Corner common to Sections 10 and 11, T42N - R26W

1852	Martin	M. Hall,	D.S.	set	а	Cedar	Quarter	section	post	and
- (pa	Cedar	ned the follo	owing \ 18''	witnes		: 41°W	2	8 Links		
554	Cedar		12"		S	28°E		9 Links		

1980± Escanaba Paper Company line notes titled "Survey to establish sec corner common to sections 10, 11, 14 and 15 - T.42N, R26W" commences at the center of County Road 426 and proceeds south. The North-South line between sections 10 and 11 list the 80.00 chains, original G.L.O. measurement. An Escanaba Paper

CARLA A L'HUILLIER REGISTER OF DEEDS MARQUETTE COUNTY, MI RECORDED ON -03/-17/2016- 03:27PM PAGES: 1 LIBER 8 RC PAGE 207 Register of Deeds Stamp & File Number



Company calculation sheet shows Latitude and Departures from a random line between sections 10 and 11 at the one quarter corner and each one sixteenth corner. The calculation sheet shows a distance of 5250 feet along the North-South line common to sections 10 and 11 and 1312.5 feet between each one sixteenth corner. The notes and calculation sheet do not indicate anything set for the corner. 1982

Larry J. Bussone, P.S. "Found a 4" post for Corner Location. Clear cutting was done to the East and South of Corner. It appears that the Mead Corp. may have set this corner." Mr. Bussone set a 1" Round Iron Bar next to 4" Post and established the following witnesses as recorded at Liber 4 on Page 185 of the Marquette County corner records:

Jesci	iption of comer evidence found a	and/or mothod anni	and the near the stand
200.00	Cen. Line of Power Line	South	132.0 feet
	Con Line of Deurselling		10.11061
12.	6" Cedar	Due No.	48.1 feet
210	0" 0 1		40.0 1661
	11" Cedar	N57°W	46.0 feet
	11" Codar		44.0 IEEL
	12 Poplar	N86°W	44.8 feet

B. D and/or method applied in restoring or reestablishing corner:

Found the 1" Iron Rod and Post as recorded. Based on the Escanaba Paper Company calculation sheet the position was midway and on line from the corner common to sections 10, 11, 14 and 15 and a point at the centerline of County Road 426, based on other monuments in the area Robert E. Schmeling, R.L.S. was involved in the retracement. The Escanaba Paper Company distance was 2625.0 feet and was measured as 2620.7 feet to the centerline of County Road 426 and measured 2619.0 to the corner common to sections 10, 11, 14 and 15, which both check reasonably well with the Escanaba Paper Company position. The section corner was recovered as a 1-1/4" bolt with 2-1/2" head, as noted by Glenn C. VanNeste on field notes, 18.2 feet south of the centerline more in accordance with the Marquette County Road Commission Plans. The 1" iron pin bears N49°W a distance of 12.58 feet from the calculated single proportionate measurement position from the corner common to sections 2, 3, 10 and 11 (I-03, a found 1-1/4" bolt with 2-1/2" head as recorded at Liber 8 of RC on page 206) and the corner common to sections 10, 11, 14 and 15 (I-05, a set Berntsen monument with cap stamped to identify the corner common to sections 10, 11, 14 and 15 (I-05, a set Berntsen monument with cap stamped to identity the corner as recorded at Liber 8 of RC on page 208). The Larry J. Bussone Cedar Bearing Trees were found as windfalls and the Poplar was found as a stump and all checked reasonably well. The centerline of County Road 426 was mistakenly utilized by the Escanaba Paper Company as the section line adversely affecting the upon the evidence and information recovered the post and 1" Iron Rod were considered a good faith effort by the Escanaba Paper Company and Mr. Bussone to re-establish the corner position and was accepted as the corner

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: The found 1" Iron Rod and Post were left in place. The corner falls in a double transmission line corridor, 16 feet

north of the northern most overhead electric line, 196 feet North of southern corridor tree line and northern corridor tree. The following Bearing Trees were established: 34 feet South of

	Comment			and the day
	Spruce	5"	N29°E	68.40 feet
	Spruce	5"	S83°W	126.50 feet
31:	Cedar	11"	N57°W	83.71 feet
Sal-	Cedar	11"	N06°W	83.73 feet
ie	measured	hearings are true	The distance line	

Th true. The distances are to set 30d nails with annigs are washers in the right side of each Bearing Tree, which are all upper and lower blazed and painted orange.

ddens 0 Signed by Surveyor's Michigan License No. 46667



Date

1 of 1

20 16 TRAN 20 TRANS A DE MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975; REVISED JAN., 1983; REVISED OCT., 1995