



SITE OF CAMP LUDINGTON-PERE MARQUETTE

HAMLIN LAKE

SAUBLE RIVER

Park Drive

Parking Area

X-SECTION THROUGH DAM
SCALE 1" = 10'

Proposed Steel Sheet Piling
Depression at this point in front of Dam
Steel Sheet Piling
South End of Dam Repaired in 1928. Now in good condition.

Without concrete apron at this point

Normal Level Lake Hamlin 594.5
Normal River Level 579.5

Entire Area of Park Composed of Fine Beach Sand to a Depth of Over 100'.
Wood Sheet Piling

Note: - Information for Dam X-Section obtained from old plans and from actual measurements.

DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE And MICHIGAN DEPARTMENT OF CONSERVATION CO-OPERATING				E-87	
BRANCH OF PLANNING		STATE PARK DIVISION			
SYMBOL		NUMBER	122	SHEET NO.	2
DRAWN BY		LUDINGTON STATE PARK SP-2 DAMS IM-POUNDING-REPAIRS		FILE NO.	
		SCALE 1" = 50'			
CHECKED		DESIGNED			
DATE		PROJECT SUPERINTENDENT	DATE		
RECOMMENDED FOR CONSTRUCTION		DATE	12/4 35		
DATE		FIFTH REGIONAL INSPECTOR	DATE		
APPROVED FOR CONSTRUCTION	6/23/32	APPROVED		SUPV. OF STATE PARKS	
DATE		FIFTH REGIONAL OFFICE S.P.S.	DATE	MICH. CONSERVATION COMM.	