

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. <u>45</u> N. S., R. <u>22</u> E. W.		<u>G-7, H-7, I-7</u>
2. PROPERTY CONTROLLING IN SECTION _____ T. _____ N. S., R. _____ E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ N. S., R. _____ E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

ALGER
Co.

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, David B. Babbitt do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on August 24 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- G-7 S.W. section corner; wood post - sugar 10 - N28°E - 12 lks.; hemlock 12 - S72°W - 25 lks.
H-7 South 1/4 corner; wood post - y. birch 8 - N23°W - 15 lks; sugar 12 - S32°E - 21 lks.
I-7 S.E. section corner; wood post - cedar 12 - N42°E - 25 lks.; y. birch 12 - S60°W - 4 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- G-7 Found 3/4" pipe - not of record but fits well with other corner monuments in the area.
H-7 Found iron pipe - not of record but it fits will with surrounding corners; replaced with D.N.R. monument.
I-7 Found old 3"x3" sq. stake with R.R. spike driven in the top of it, in old road grade (N.W. - S.E.) point of stake in good condition under road fill. Parts of old cedar stump in right position for N.E. O.B.T.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- G-7 1" pipe, 4" aluminum cap; 10" spruce - N52°W - 19.1'; 10" maple - S56°W - 27.6'; 10" maple - S80°E - 1.5'; 14" hemlock - N25°E - 40.1'
H-7 1" pipe, 4" aluminum cap and cedar post; 12" hemlock - S10°E - 57.4'; 13" hemlock - N47°W - 46.6'; 8" ironwood - S62°W - 30.4'; 9" maple - S32°E - 5.95'
I-7 1" pipe, 4" aluminum cap and cedar post; 10" w. ash - N85°E - 11.75'; 20" cedar - N05°E - 49.25'; 10" cedar - S35°W - 41.5'; 16" cedar - S61°W - 40.55'.

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558