

JAN 18 2001

Approved by Alger County  
Land Survey Monumentation  
Peer Group Under Act 845 of  
P.A. of 1990 On 12-13-2000

*Harold Atkinson*  
Chairman

05-216

For corners in SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Alger (County)	Located In:	Corner Code #
	48N 15W	K07
1. Public Land Survey	T <u>      </u> R <u>      </u>	<u>      </u>
	T <u>      </u> R <u>      </u>	<u>      </u>
	T <u>      </u> R <u>      </u>	<u>      </u>
	T <u>      </u> R <u>      </u>	<u>      </u>
2. Property Controlling in Section	S <u>      </u> T <u>      </u> R <u>      </u>	<u>      </u>
	S <u>      </u> T <u>      </u> R <u>      </u>	<u>      </u>
3. Miscellaneous Property in Section	S <u>      </u> T <u>      </u> R <u>      </u>	<u>      </u>
	S <u>      </u> T <u>      </u> R <u>      </u>	<u>      </u>
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

FILED  
TIME 8:50 AM

DEC 20 2000

DONALD W. KINNUNEN  
REGISTER OF DEEDS  
ALGER COUNTY, MI  
Register of Deeds Stamp & File Number

I, Robert L. Jamros, in a field survey on September 28, 2000,  
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current  
manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  
5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, recovered, found  
as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

**K07:** PLS Geo. E. Adair, DS, 1851. Set post corner of Sections 13, 14, 23 and 24. Tamarack  
10", S.45°E., 49 links. Spruce 7", N.56°W., 31 links. \*\*\*\*\* C.C.I. Co. Ray J. Brotherton,  
RLS, 1947. Set 3" Tamarack post from Government Tamarack BT stump, iron marks plain. Spruce  
6", N.55°W., 24.1 feet. Spruce 5", S.45°E., 26.5 feet. Unrecorded report of 1963. \*\*\*\*\* No  
other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

**K07:** Found 3" Tamarack post with squared top down and under swamp moss and muck. Found  
point of post in muck 10" below top of moss. 6" Spruce BT bearing Northwest, now a decayed  
stump. 5" Spruce BT bearing Southeast from corner post, standing green. Existing post point  
at corner position as found is accepted as a careful and faithful perpetuation of the  
position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**K07:** Set 2½" x 30" Berntsen aluminum monument no. A1NB30 with ¾" aluminum cap stamped to  
identify corner position, over as found 3" Tamarack post point. Renewed existing NBT with BT  
signs and paint. Established new reference trees with BT signs, blazed, scribed, and  
painted. Set PK nails for measure with aluminum I.D. washers in the following: Ex. NBT,  
Spruce 7", S.37°E., 26.87 feet (blaze scars); Tamarack 6", S.37°W., 28.62 feet (S23 BT);  
Tamarack 6", N.56°W., 20.84 feet (S14 BT); Tamarack 9", N.44°E., 27.72 feet (S13 BT).  
Survey marker sign on 6 foot steel post, S.79°E., 1.0 feet. All bearings are magnetic.

Signed by *Robert L. Jamros* Date Dec. 17, 2000  
Surveyor's Michigan License No. 25849

