

# SURVEY & MONUMENTATION

JAN 18 2001

Approved by Alger County  
Land Survey Monumentation  
Peer Group Under Act 345 of  
P.A. of 1990 On 12-13-2000

Harold W. Carlson  
Chairman

For corners in

SECTION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Alger  
(County)

Located In:

Corner Code #

1. Public Land Survey
 

T	48N	R	15W	M08
T	48N	R	14W	A08 ✓
T		R		
T		R		
2. Property Controlling in Section
 

S		T	R	
S		T	R	
3. Miscellaneous Property in Section
 

S		T	R	
S		T	R	
4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

FILED

05-219

TIME 8:50 AM

DEC 20 2000

DONALD W. KINNUNEN  
REGISTER OF DEEDS  
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Robert L. Jamros, in a field survey on October 20, 2000  
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M08: PLS William A. Burt, DS, 1841. Set quarter section post. Birch 14", S.57°W., 10 links. Spruce 10", N.30°E., 58 links. \*\*\*\*\* No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M08: Established corner position at midpoint and on line between section corners 1/2 mile North and South. Found very faint paint lines of timber cruisers North and West from this position. No original G.L.O. evidence was found. Corner position as established is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M08: Set 2 1/2" x 30" Berntsen aluminum monuments no. A1NB30 with 3/4" aluminum cap stamped to identify corner position. Established reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Hemlock 8", N.02°W., 27.58 feet (1/4S BT); Hemlock 10", N.67°E., 26.41 feet (1/4S BT); Hemlock 11", S.21°E., 19.81 feet (1/4S BT); Hemlock 15", S.65°W., 33.14 feet (1/4S BT). Survey marker sign on 6 foot steel post, S.65°E., 0.80 feet. All bearings are magnetic.

Signed by

Robert L. Jamros

Date

Dec. 17, 2000

Surveyor's Michigan License No.

25849

