LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	_ Located In:	Corner Code #	. YF
1. Public Land Survey	TR		
 Property Controlling in Section Miscellaneous Property in Sec. 	S 24 T 48N R 31W S T R S 24 T 48N R 31W S T R S T R	16 (GCDB 660300) PCC N. of #16 (GCDB 660312)	
4. Lot No. , Red 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number A B C D E F G K I J K L M 2 6 5 5 4 3 2 1
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, monumented, recovered, found as expressed below:			
NOTE: Not more than 2 corr on this certificate.	ners, all in the same town and range,	, may be recorded	11 12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:			
(16-Sec 24) Past 1/16 corner between Costions 24 and 25 Mbs second 25 July 2			

East 1/16 corner between Sections 24 and 25. The corner was previously established on March 17, 2010 by the undersigned at a position derived using the proper method but based on an incorrectly positioned monument at Section corner M9. The proper position for M9 was remonumented in 2015 by Gerald Carlson PS for the Marquette County Remonumentation Program, necessitating the removal of this monument to its proper place.

(PCC N. of #16) The intersection of the East 1/16 line of Sec. 24 with the southerly R/W line (50.00' as measured at right angles from the track centerline) of the former DSS&A Railway. The corner was previously established on March 16, 2010 by the undersigned at a position derived using the proper method but based on an incorrectly positioned monument at Section corner M9. The proper position for M9 was remonumented in 2015 by Gerald Carlson PS for the Marquette County Remonumentation Program, necessitating the removal of this monument to its proper place.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(16-Sec. 24) Established the position for the corner midway and on the Section line between the Section corner (remonumented in 2015) 1327.63' east and Quarter corner of record 1327.63' west. Destroyed the 2010 monument.

(PCC N. of #16) Monumented the corner on a straight line between monumented 1/16 corner #16, Section 24 and unmonumented 1/16 corner #9, Section 24, at its intersection with the southerly RR R/W line, said intersection being 829.37' north of 1/16 corner #16. Destroyed the 2010 monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(16) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. (PCC) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: Set measuring nail with MDNR tag in the side of: 9" Spruce N69°E 14.25' mrkd "1/16S BT" 11" W.Birch S27°E 17.7' mrkd "PCC BT" 16" Maple S18°W 4.65' 12" W.Pine S24°E 29.45' do ďО 8" Maple N64°W 23.25' do 4" Sugar S01°W 8.15' do 9" double Maple N22°W 28.2' 9" Balsam N48°E 15.0' do do Set sq'd cedar post adjacent. Set sq'd cedar post adjacent.

Bearings are magnetic.

Signed by

Surveyor's Michigan License No.

33986

01/25/2016

LAND SURVEYOR

STEPHAN J SZYSZKOSKI

OF MICH

No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

LESKICHA PORMAZQU FORM APPROVED BY MICHIGAN STATE BOARD OF