LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name:	eyor's Name: <u>Stephan J. Szyszkoski</u>			Field Survey Date:		August 15, 2017					
For corner(s) in:	Baraga		County	AB			з н		K L M.		
Original Public Land Survey Corner S T R<		Corner Code Corner Code B6 (GCDB 1404	2 3 4 5 6-1	2 6 3 4 7 5	5	9	10	11	12 4 13 6 13 6	; ;	
b. S 18 S S	T 48N R 31W T R T R	9 (GCDB 160		8 19 9 30 11 12 31	29	28 -33	22 - 27 - 34	23 26 35	24 8 9 - 25 1 1 36 1	0	
Part A. Corner His	story			A B	CDE	= F (3 H I	J	K L M'	J	

- a.) Center of Section 18. Not established in the original survey. Corner recorded in 2008 by Sven Holmquist PS #52474 as having been established at the intersection of 1/4 lines (survey rec. GR 2008/5895, Baraga Co.)
- b.) Center-East 1/16 corner, Section 18. Corner recorded in 2008 by Sven Holmquist PS #52474 as having been established midway and on line between B6 and C6 (survey rec. GR 2008/5895, Baraga Co.).

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

- a.) Established the position for the corner at the intersection of 1/4 lines of Section 18. From the position thus established, I found the 2008 monument of record N88 1/2°W 15.6' distant. The erroneous location of the 2008 monument is a result of a bad measurement, made in 2008, to corner C7, the position of which was subsequently used by Mr. Homquist to calculate the position of B7 and the subdivision of the section. Drove the 2008 monument flush to the ground surface.
- b.) Established the position for the corner midway and on a straight line between Center of Section 1325.58' west and Quarter corner 1325.58' east. From the position thus established I found the 2008 monument of record N89°W 7.7' distant. The erroneous location of the 2008 monument is a result of a bad measurement, made in 2008, to corner C7, the position of which was subsequently used by Mr. Holmquist to subdivide Section 18. Attempted to drive the 2008 monument below ground but was not successful due to subsurface rock. Therefore, it was left in place.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

a.)Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 5" Maple NO5°E 6.1' mrkd "C1/4 BT" 4" Balsam S50°E 4.95' do 7" Balsam S07°W 9.6' do 5" Maple N70°W 17.3' do Set sq'd cedar post adjacent. E= 7905604.540 N= 197835.849	b.) Set 1"IDx28" I.pipe with 2" set measuring nail with MDNR tag 8" Sugar N27°E 33.45' 4" Sugar in clump N85°E 5.0' 3" Sugar S54°W 12.8' twin 7" Sugar N69°W 14.4' Set sq'd cedar post adjacent. E= 7906008.313 N= 197823.488	alum. MDNR cap. in the side of: mrkd "1/16S BT" do do do
--	---	---

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum
Coord. Ref.=NGS PID AA8080: N=192972.689 m. E= 7925456.741 m.

A 22 / 26 / 2000 III. E= 7929430.741

Professional Surveyor's License No.:

33986

page 1 of 1

Prepared By:

S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908

STEPHAN J.
SZYSZKOSKI
PROFESSIONAL
SURVEYOR
No.
33986