LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For comers in

Baraga (County)	_ Located In:	Corner Code #	
1. Public Land Survey	T 48N R 33W T 48N R 33W	H7	
2. Property Controlling in Section	S = T = R = S = T = R		
3. Miscellaneous Property in Sec.	S T R S T R		
4. Lot No. , Red 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number
		20/2011	2 - 6 5 4 3 2 1 - 1
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey 5			
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 18 17 16 15 14 13 a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7			
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			9 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			
			12 31 32 33 34 35 36

- A. Description of original monument and accessories and/or subsequent restoration:
- (H7) Quarter corner common to Sections 15 and 22. 1852 Established by Francis Houck Deputy Surveyor midway and on the Section line between Section corners 40.00 chains east and west. post. Tamarack 10" N59E 38 links, Spruce 10" S24W 24 links. Found no subsequent record.
- (I7) Corner common to Sections 14-15-22-23. 1852 Established by Francis Houck Deputy Surveyor. Monument not noted. Tamarack 12" N45E 38 links, Tamarack S56W 47 links. The original plat gives distances 120.00 chains north to I4, 79.90 chains south to I9, 80.00 chains west to G7, and 80.00 chains east to K7. Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (H7) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the corner midway and on the Section line between monumented Section corners of record 2628.39' east and west.
- (I7) The original corner position now falls in an artificial impoundment, inaccessible, and no physical evidence of the corner position is to be found. Reestablished the position for the corner by double proportionate measurement to the original record between Quarter corner I4 7922.37' north, Section corner I9 5275.00' south, and Section corners G7 and K7 5256.78' west and 5256.66' east, respectively. Established a witness corner 180.00 feet north of the corner position on the Section line between I7 and I5 (I5 being a position computed by double proportionate measurement to the original record, not monumented).
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Date 08/15/2011 Surveyor's Michigan License No. 33986 For the Michigan Department of Natural Resources, Forest Management Division

STEPHAN J SZYSZKOSK LAND SHRVFYOR 14. 1975

sed Jan., 1983