## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #	81					
1. Public Land Survey	T 49N R 34W T 49N R 34W	F13 G12	O					
2. Property Controlling	STR							
in Section	S T R	- n						
3. Miscellaneous	s		<del></del>					
Property in Sec.	S							
4. Lot No. Red	corded Plat		Register of Deeds Stamp & File Number					
5. Private Claims			A B C D E F G H I J K L P					
			2 6 5 4 4 3 2 1 2 1 - 1					
ı, Stephan J. Szyszkoski , in	a field survey on 06/	05/13 do hereby state	3					
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2								
	egulations and rules therefore as required							
	instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 18 17 16 15 14 13 a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7							
	of Land Surveyors or by a Decree							
re-established, monumented, recove	ered, found as expressed below:	9						
		10 30 29 28 27 26 25						
	ers, all in the same town and range,	11						
on this certificate.			12 31 32 34 35 36					
			13					

- A. Description of original monument and accessories and/or subsequent restoration:
- (F13) Quarter corner common to Section 33 T49N-R34W and Section 4 T48N-R34W. 1846 Established by Wm.A. Burt Deputy Surveyor midway and on the Township line between Section corners 40.00 chains east and west. Set Tamarack post. Tamarack 4" N60°E 15 links, Tamarack 4" N16°W 13 links. Found no subsequent record.
- (G12) Quarter corner common to Sections 33 and 34. 1853 Established by Francis Colman Deputy Surveyor on the Section line between Section corners 39.79 chains south and 39.78 chains north. Set post. W.Pine 6" N40°E 23 links, Spruce 8" S37°W 45 links. Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (F13) The original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the position for the corner on the Township Line between Section corners 2640.88' east and west, being proportionate to the original record.
- (G12) The original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the position for the corner on the Section line between Section corners 2618.33' south and 2617.67' north, being proportionate to the original record.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F13) Set 1"IDx32" I.pipe wit Set measuring nail with MDNR 3" W.Birch S84°E 46.75' m	tag in the side of:	(G12) Set 1"IDx32" I.pipe wi Set measuring nail with MDNR 4" J.Pine NO8°W 16.3' mrk	tag in the side	cap. of:
3" Tamarack S05°E 31.4'	do	3" Tamarack N67°E 34.85'	do	
4" B.Spruce N73°W 41.15'	do	4".J.Pine \$35°E 8.7'	do	
6" B.Spruce N41°W 50.65'	do	5" R.Pine S81°W 35.6'	đo	
Set sq'd cedar post adjacent.		Set sq'd cedar post adjacent		
E = 7880147.835 $N = 202321.8$	31	E= 7880978.068 N= 203102.		

Bearings	are magne	tic.	Coordina	ates	are	MCS83	in	meters	(NAD83 (2011)	Datu
Coord.	. Ref.=NGS	PID	RL0476:	N= 3	19648	32.411	m.	E= 7879	234.516 m	#

Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Surveyor's Michigan License No. 33986

Date 08/06/2013

For the Michigan Department of Natural Resources, Forest Resources Division

FORM APPROVED BY MICHIGAN STATE BOARD OF P. SEE RO

STEPHAN J. SZYSZKOSKI LAND SLIRVEYOR NO. 33986

Revised Oct., 1995