LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in Baraga Located In: Corner Code # 1. Public Land Survey Т 50N R 34W A11 R 50N 34W **B11** Т R 2. Property Controlling S R in Section S R S 3. Miscellaneous S Т R Property in Sec. S Register of Deeds Stamp & File Number 4. Lot No. , Recorded Plat 5. Private Claims i, Stephan J. Szyszkoski , in a field survey on 06/11/13 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey 5 instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, g re-established, monumented, recovered, found as expressed below: 10 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: (All) Corner common to Sections 30-31 T50N-R34W and Sections 25-36 T50N-R35W. 1959 - Billy D Buckler RLS remonumented the corner at record bearing and distance from the stump of an original B.T. Y.Pine S50°W 18 links. Set 1" pipe with 4" brass cap. 9" R.Pine N14°E 54 links, 9" W.Fine N25°W 112 links, 8" Soft Maple S57°W 15 links. 1979 - Corner monument recovered and accepted by R.L.Drahn RLS, who noted the following NBTs: 12" Red Maple N60°W 21.3', 6" Aspen S30°E 3.9', 10" Red Maple S60°W 10.8', metal sign post S85°W 2.2' (See L.4 of LCR, P.2). (B11) Quarter corner common to Sections 30-31. 1962 - Reestablished by Billy D. Buckler RLS by proportionate measurement to the original record between Section corners 1/2 mile east and west. Set 1" iron pipe with 4" alum. cap. 7" W.Birch N89°W 03 links, 7" W.Birch S59°E 25.5 links. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (All) Found the 1959 monument in good condition and at record bearing and distance from the remains of the 1959 9" R.Pine N14°E, from the 1979 Maple witnesses, recovered in good condition, and from the metal sign post. The NBT Aspen S30°E and W.Pine N25°W are now gone. Accepted the monument as a careful and faithful perpetuation of the position of the original corner. (B11) Found the 1962 monument in good condition and at record bearing and distance from the 1962 NBT Y.Birch (recorded as a W.Birch) N89°W 03 links, in good condition with overgrown blazes. The monument is S61°E 11.2' from the proportionate position between A11 and C11 and I accept same as a careful and faithful reestablishment of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (All) Found 1"ID I.pipe with 4" brass MI Dept. of (B11) Found 1"ID I.pipe with 4" alum. Mt Dept. of Conservation cap. Set measuring nail with MDNR tag Conservation cap. Set measuring nail with MDNR in the side of: tag in the side of: 9" Maple S64°W 10.6' old blazes (1959 NBT) 13" Y.Birch N86°W 2.15' old blazes 12" Maple N56°W 21.15' scribing visible (1979 NBT) (1962 NBT) 8" Balsam N74°E 14.05' mrkd "1/4s NBT" 6" Maple N74°E 30.15' mrkd "S30 NBT" Maple S44°E 14.05' do 6" W.Pine S22°E 12.1' mrkd "S31 NBT" 4" Oak S25°W 13.8' do metal sign post is N84°W 2.2' Set sq'd cedar post adjacent. E= 7876475.856 N= 213593.297 E= 7877214.126 N= 213576.238 Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum). Coord. Ref.=NGS PID DI1837: N= 221257.624 m. E= 7884435.168 m.

Signed by

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESS

07/02/2013

Date

33986

For the Michigan Department of Natural Resources, Forest Resources Division

STÉPHAN J.

SZYSZKOSKI

AND

SURVEYOR

33986

Revised Jan., 1983

10