LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

F	*		
For	COL	1 Arc	10
1 01	CULI	1012	

Surveyor's Michigan License No.

Baraga	Located In:							
(County)	Located in:	Corner Code #						
1. Public Land Survey	T 50N R 34W T 50N R 34W	B7 B5						
2. Property Controlling in Section	S T R S T R							
3. Miscellaneous Property in Sec.	S T R S T R							
	orded Plat	L		Register of Deeds Stamp & File Number				
5. Private Claims				D E	FG	HI	3	KL
ı, Stephan J. Szyszkoski , in :	a field suprement	100.142	3 1	Ì		- 3	†²	1-1-1-
		do hereby state	4	- 8	<u> </u>	-10	1	1-12
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey 5								
instructions of the United States De	6 -18-	-1/7	16-	15-	<u> </u>	13-		
a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8			7	+	+		╁┪	
re-established, monumented, recover	red, found as expressed below:			20	21-	22	+2	3
			9		 -	1-1	++	
NOTE: Not more than 2 corne	ers, all in the same town and range,	may be recorded	10 - 30 -	-29	28-	-27	†²(5
on this certificate.			2 31	32	333		Ţ,	
A Description of original		•				Ĭ	ĮΪ	
(B7) Quarter corner co	nument and accessories and/or sommon to Sections 18 and 1 and reestablished same by some Set 1" pipe with 4" alu	19. 1961 - Billy D. Bu	SAGIIYAMAY	+ hate		والمتعاملات	. l .	
Postcion at record bea	ommon to Sections 7 and 18 aring and distance from the 12" S42°W 20 links. Set S31°E 43.5 links.	ne remains of two Oxida	inal bass	وريد المساهرة		a 1	1 .	
B. Description of corner evid	lence found and/or method applie	ed in restoring or reestablishi	ng corner:		3			
(B7) Found the 1961 mo position. Mr. Buckler 19 which resulted in t monument at A7 being i positions at either A7	nument in good condition, seems to have made a meath is monument being instal anstalled S74°W 36.4' from or B7 and reestablished on Section corners 2412.77	apparently undisturbed assurement error along the lled S44°W 26.5' from the months that the intended position	ed, but inthe line the internal did	betwee ded po l not a	n Sec sitio ccept	tions n, ar the	19	the 61
TOO HOT HOW B TO SUG	nument in good condition ar N06°E 07 links in good and faithful perpetuation	1 COndition with Avera	ratio blas			he re ed th	ema:	ining
C. Description of monument	for corner and accessories establ	ished to perpetuate locating	the position	of the	corner:			
Set measuring nail wit 4" Sugar N09°E 11.55' 18" Hemlock S23°E 4.95 17" Sugar S53°W 21.35' 17" Sugar N75°W 15.05' Set sq'd cedar post ad	do do	(B5) Found 1" I Conservation captag in the side 13" Sugar N06°E 5" Basswood S74 7" Sugar S04°W 12" Sugar N48°W Set sq'd cedar E= 7877319.927	p. Set mof: 4.95' °E 12.95 28.4' 39.2' post adja	old bl	ing na Lazes ckd "1	iil w:	th 66	MDNR NBT)
Bearings are m	magnetic. Coordinates are	e MCS83 in meters (NAD	83 (2011)	Datum	The state of the s	0.	23	CA AND
Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum) Coord. Ref.=NGS PID DI1837: N= 221257.624 m. E= 7884435.168 m.								

Date

ror the Michigan Department of Natural Resources, Forest Resources Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SORY TORSOLANDER, 1971

A D C Revised Jan., 1983

Revised Jan., 1983

07/02/2013

Revised Oct., 1995