LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga	Located In:	Corner Code #	
(County)			4)
1. Public Land Survey	T 51N R 32W T 51N R 32W	MC S. of E1	
2. Property Controlling in Section	S T R S T R		2
3. Miscellaneous Property in Sec.	S T R S T R		
4. Lot No. , Re-	corded PlatMC 08/	/30/2011	Register of Deeds Stamp & File Number
above were in conformance with instructions of the United States a Court of Law and /or that the the rules of the Michigan Boar	74, Michigan P.A. of 1970, the corner regulations and rules therefore as requirement of the Interior, Bureau of 1 corner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree	points mentioned in lines 1 and 2 red in the current manual of survey and Management or by a decree of d 5 above were in conformance with	, 5 , 6 , 7
NOTE: Not more than 2 corr on this certificate.	ered, found as expressed below: ners, all in the same town and range	e, may be recorded	9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

(MC) Meander corner on the Section line between Sections 4 & 5 at Keweenaw Bay. 1845 - Established by D.Houghton Deputy Surveyor during the original subdivision of this township, 29.78 chains South of the Section corner. Found no subsequent record.

(G2) Quarter corner common to Sections 3 and 4. 1986 - Corner position reestablished by proportionate measurement and monumented by Stephen D. Douglas, U.S. Cadastral Surveyor, in a dependent resurvey of this township for the Bureau of Land Management. Set 5/8"x36" alum. post, capped. W.Birch 7" S08E 57.5 links, W.Birch 8" N87W 25 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(MC) All evidence of the original post and accessories has been destroyed by road construction. Found no evidence of subsequent monumentation. Reestablished the corner at record distance (1965.48') from section corner El on a true bearing from El of S 00 deg. 24'30"E. This bearing was determined by Stephen D. Douglas, U.S. Cadastral Surveyor, during the 1985-6 dependent resurvey of this township "...resulting from an index correction for Deputy Mellons' [sic] survey". The position for the corner cannot be properly monumented. I established a WITNESS CORNER to the MC 114.37' north of the MC position on the Section line, the position also being on the northerly 33.0' R/W line of Pequaming Road.

(G2) Found the 1986 monument in good condition and at record bearing and distance from the 1986 W.Birch witnesses. Accepted same as a careful and faithful reestablishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(MC) Set 1"IDx32" I.pipe with 4" alum. MDNR cap for a WITNESS CORNER to the original M.C. which is 114.37' south of the monument.

Set measuring nail with MDNR tag in the side of: 2" Tamarack N30E 49.59' mrkd "WC BT" 3" Tamarack S77E 62.39' do Power Pole S25E 88.06' Power Pole N33W 241.86' Bearings are magnetic.

(G2) Fd. 5/8" dia. alum. post with BLM cap. Set measuring nail with MDNR tag in the side of: 7" W.Birch S04E 37.7' mrkd "1/4S NBT" (1986 NBT) 10" W.Birch N82W 16.35' do do 7" twin Maple N26E 13.7' do 11" Maple S32W 46.75' do Set sq'd Cedar post adjacent. Bearings are magnetic.

			1
Signed by Styphan Ingglish.	Date	01/25/2012	1
Surveyor's Michigan License No. 33986			17
For the Michigan Department of Natural Resource	s. Forest Managemer	at Division	1

n Department of Natural Resources, Forest Management Division

16812 16811 FORM APPROVED BY MICHIGAN STATE BOARD

Rervised Oct 1995

MICH

STEPHAN J SZ<u>YSZKOSK</u> LAND SURVEYOR

CAND SO