7

Filing Requirement of Act 74, Mich. PA 1970 LIBER 276

SECTIO	N		COATE OF WIGHTON
For Corners In: Benzie (County)	Located In	Corner Code#	STATE OF NICHIGAN BENZIE COUNTY RECORDED
1. Public Land Survey	T <u>26N</u> R <u>13W</u> T R		12 JAN 2000 9:22:26 AM
Property Controlling in Section	S T R		MICHELLE R. GRAY REGISTER OF DEEDS H PAGES ONE.
Miscellaneous Property in Section	S T R		Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:	· · · · · · · · · · · · · · · · · · ·	A B C D E F G H I J K L M
5. Private Claims:			2 - 6 - 5 - 4 - 3 - 2 - 1 -
I, <u>Craig W. McVean</u> , in a field survey on <u>November 3</u> , 1999 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:		oints mentioned in rules therefore as States Department Court of Law and/or conformance with of a Court of Law;	3 4
NOTE: Not more than a be recorded on this cer	2 corners, all in the same town ar rtificate.	nd range, may	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36 1
A. Description of original G6 – GLO – Set ¼ post-Sugar 14" S41°E 57 L., S-D.F. Holden – 1876 – SSet from original bearing -C.P. Tuller – 1900 – L. FND. 2 Wit. Trees and P-C.P. Tuller –1903 – L.1, Chained S from G6 to G	m. Bk. P. 113 – Sec. 15 ps 1, P. 8 – Sec. 16 Post , P. 22	-Benzie Co. Found where and charcoa wood place S70°E 72.77 LCRC L. 1, rd. surface N85°W 34.9	Rd. Comm. – 1973 – Dug hole across road with Drott – e a wooden post had been, sm. pieces of rotten wood il to a depth of 2', soft spot in ground 6" below rotten ed 2' of 1" pipe, 6" R. Pine S36°E 99.94', 6" R. Pine 7, steel fence post S29°W 61.03 P. 164 – H. Bruning – 1982 – FND. Iron stake below raised w/ iron rod & Plas. R.L.S. Cap. Fence cor. post 5', PP S12°E 116.70', R. Pine S60°E 60.80' L.1, P.891 – H. Bruning – 1987; L.2, P.903 –
•	evidence found and/or method app		stablishing corner: sipe per Benzie Co. Rd. Comm., LCRC & Rec.
Surveys Iron Pine	was down 2' in CL of N-S Gravel I	Rd. Fence to W and fits	s fence remains projected from the East. ½" rebar in and faithful perpetuation of the position of the original
			Ratified by Peer Group In accordance with P.A. 345 Chairman Date 11/2/1999
C. Description of monum	nent for corner and accessories est	ablished to perpetuate I	locating the position of the corner:
Brass Cap on ¾" x 36" in N44°E 200.84' to NW co S71°E 72.82' to set N & S67°E 60.73' to set N & S36°E 100.19' to set N & S18°E 116.57' to FD. N	T in N. side 12" R. Pine (BCRC) T in N. side 10" R. Pine (HB) & T in SE side 12" R. Pine (BCRC) & S in E side UP (HB) I in S. side Wood Gate Post	'Benzie Co. Remon.' ete cylinder – down 0.6'.	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR NO. 39088
Signed by: Surveyor's Michigan	acy W. Me Ver License No.: 39088	Date:	12/8/1999