

Land Corner Recordation Certificate
Attachment B to 2016 Annual Grant Agreement
 Authority: MCL 54.205 and R54.202

This form is **ONLY** for corners filed under the 2016 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 – 54.210d and 2016 State Survey and Remonumentation Grant Agreement

Notes:

- No more than two Original Public Land Survey Corners can be recorded on this certificate
- If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
- If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county

For corner(s) in: Benzie County

Homestead Twp.

Corner Type	Survey Township		Corner Code															
Original Public Land Survey Corner	T	R		1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
• MCL 54.202(g)	T	R		2		6		5		4		3		2		1		2
• MCL 54.262(g)	T	R		3														3
	T	R		4		7		8		9		10		11		12		4
	T	R		5														5
Property Controlling Corner	S	T	R	6		18		17		16		15		14		13		6
• MCL 54.202(i)	S	T	R	7														7
• MCL 54.262(h)	S	T	R	8		19		20		21		22		23		24		8
	S	T	R	9														9
Protracted Public Land Survey Corner	T	26N	R 14W	H1	10		30		29		28		27		26		25	10
• MCL 54.202(k)	T	R		11														11
• MCL 54.262(i)	T	R		12		31		32		33		34		35		36		12
	T	R		13														13

Part A: Corner(s) History

- H1** – Closing N. ¼ Corner common to Sec. 3, T26N, R14W –
- 1897 – County Survey Record – Small Liber, p. 194 – J. A. Pettitt – Petition Survey Sec. 3. – East at 40.05 intersect 30 N of ¼ post. Thence East from ¼ S. @ 40.02 intersected 44 N of NE corner.
 - 1973 – Record Survey L. 1, p. 304, H. R. Bruning PS #10681 – Shows corner
 - 1974 – LCRC L. 1, p. 91 – H. R. Bruning PS #10681 – Set PK nail by single proportionate between G1 and I-1.
 1) 30" Maple S43°E 39.00'; 2) 24" Maple S66°E 34.42'; 3) Tel. pole S60°W 81.10'; 4) Road P.I. I.B. N30°W 12.09'
 - 1975 – LCRC – L. 1, p. 101 – C. F. Roser, PS #12028 – Found PK and replaced with 1 1/8" x 18" iron rod.
 1) 30" Maple S43°E 39.00' 2) 24" Maple S66°E 34.42'; 3) T. Pole S60°W 81.1'; 4) RR spike (Rd. PI) N60°W 12.09';
 5) Set Cedar post w/ loc. tag S10°E 23'
 - 1997 – LCRC L. 1, p. 334 – C. Kiiskila, PS #33981 – Fd. 1 1/8" x 18" iron rod.
 2) 28" X. Maple S66°E 34.30'; 1) 34" Maple S43°E 39.00'; 4) Fd. RR spike (Rd. PI) N60°W 12.03';
 6) Set Carsonite Post with loc. tag South 33'; 7) S ¼ Sec. 34, T27N, R14W Benzie Co. Remon. Mon. in Mon.
 Box is N89°20'W 10.20;

