SURVEY & REMONUMENTATION

APR 0 7 1998

SECTION

Chippewa County Remonumentation Corner LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Chippewa	Located In:	Corner Code #
Public Land Survey	T <u>45N</u> R <u>1E</u> T R T R	<u>F-5</u>
2. Property Controlling in Section3. Miscellaneous Property in Sec.	S T R S T R S T R S T R	
4. Lot No, Ro	ecorded Plat	


\$7.00 LAND CORNER \$2.00 MSSR 14 Jan 1998 3:36:36 PM Receipt #5566 RECEIVED FOR RECORD CHIPPENA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 10 PAGE 124

Register of Deeds Starnp & File Number

I, Larry R. Rogers, in a field survey on October 22, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

(F-5) 1/4 Corner Common to Sections 9 and 16, T.45 N., R.1 E.

Original corner post was placed in September, 1845 by James H. Mullett. 1921 survey by County Surveyor found no evidence of original corner position. A 1996 survey by Ronald Bischer, P.S. 22428, restored position midway and on line between Section corners to East and 71A CO.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F-5) 1/4 Corner Common to Sections 9 and 16, T45 N., R.1 E. This corner is being re-established as part of the Chippewa County Remonumentation Program.

VAMIN *Republik*a pangk Found no evidence of original corner position or 1996 Bischer corner. Replaced corner midway and on line between Section corners to East and West. Corner now falls in manmade fish rearing pond and will be under water about six months every year. The pond is drained every

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F-5) 1/4 Corner Common to Sections 9 and 16, T.45 N., R.1 E.

Corner is a 3/4" x 24" iron pin with plastic remonumentation cap. Corner falls in manmade fish rearing pond.

Witnesses: Northeast Corner Section 16 East 1/4 Corner Section 16 South 1/4 Corner Section 16 West 1/4 Corner Section 16 1" iron pipe with cap 1" iron pipe with cap

N87'26' 28"E 2650.901 S47°32' 58"E 3676.88 S01'35' 01"F 5272.93' S42°38' 06"W 3793.64 N87°26' 20"E 306.95 S01°35' 01"F 109.37

Date

OF MICHIG ARRY R. ROGERS and Surveyo NO. 29251 AND

file

Surveyor's Michigan License No. 29251

NOTE: All bearings are compass bearings. All distances are to a nail in side of witness objects unless noted.

Signed by