PR - 12/12/97

SURVEY & REMONUMENTATION

APR 07 1998

Chippewa County Remonumentation Corner LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	corners	in


SECTION

Chippewa	Located In:	Corner Code #	\$2.00 MSSR 14 Jan 1998 3:43:01 PM Receipt #
1. Public Land Survey	T <u>45N</u> R T R T R T R	1E H-5	RECEIVED FOR RECORD CHIPPENA COUNTY - STATE OF MICHIGA SHARON H. KENNEDY, REGISTER OF DEE
Property Controlling in Section	S T R		BOOK 10 PAGE 131
3. Miscellaneous Property in Sec.	S T R S T R		
			Register of Deeds Stamp & File Number
	orded Plat		-
5. Private Claims			4 8 9 9 5 5 5 5 5 5

\$7.00 LAND CORNER 2.00 MSSR 4 Jan 1998 3:43:01 PM Receipt #5566 RECEIVED FOR RECORD CHIPPEWA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS OOK $10\,$ PAGE $131\,$

I, Larry R. Rogers, in a field survey on October 22, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below

Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

(H-5) 1/4 Corner Common to Sections 10 and 15, T.45 N., R.1 E.

Original corner post was placed in September, 1845 by James H. Mullett. Very little information in County Surveyor notes. Corner apparently reestablished in recorded 1996 survey by Ronald Bischer, P.S. 22428, on line between Section corners to East and West and on extension of fenceline to South. Corner falls 1' East of a split of the distance between said Section corners.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(H-5) 1/4 Corner Common to Sections 10 and 15, T45 N., R.1 E. This corner is being re-established as part of the Chippewa County Remonumentation Program.

S05°W

Found 1/2" iron, from Bischer survey, in centerline of 14 Mile Road. Accepted corner position as found.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

33.14

(H-5) 1/4 Corner Common to Sections 10 and 15, T.45 N., R.1 E.

Corner is a 1/2" iron pin in the centerline of 14 Mile Road.

8" Red Pine N63'W 58.67 10" Red Pine N40'E 37.80 6" Maple S61'E 30.72 12" Red Pine S74'W 51.87

Corner fence post



Surveyor's Michigan License No. 29251

NOTE: All bearings are compass bearings. All distances are to a nail in side of witness objects unless noted.

19

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995

Signed by