

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970
Chippewa Co. Three Corners.

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>45</u> ^{N.} S. , R. <u>1</u> ^{E.} W.	K-5
2. PROPERTY CONTROLLING IN SECTION <u>14</u>	, T. <u>45</u> ^{N.} S. , R. <u>1</u> ^{E.} W.	2-Sec.14 13-Sec.14
3. MISCELLANEOUS PROPERTY IN SECTION _____	, T. _____ ^{N.} S. , R. _____ ^{E.} W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 6-28 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
K-5 Sec. Cor. 11-12-13-14, Set by James H. Mullett, D.S. 1845.
Bearings were: Sugar 20", S71°E, 32 lks. and Maple 18", N37°W, 10 lks.

2-Sec.14 East 1/16 Corner, on North side Section 14.

13-Sec.14 South-East 1/16 Corner, Section 14.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
K-5 Corner replaced at old wood post. Found several old blazes facing corner, no positive evidence of original corner. Calls to swamp and marsh edges check well with record.

2-Sec.14 Corner placed midway bet. Sec. Cor. to East and $\frac{1}{4}$ Cor. to West.

13-Sec.14 Corner placed at intersection of lines quartering the South-East quarter section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Placed 1" pipe with 4" aluminium cap at all corners.

K-5 New bearings: 16" Y. Birch, S54°E, 7.3' and 10" Hard Maple, S79°W, 13.0'

2-Sec.14 Bearings: 20" W. Pine, S24°W, 35.1' and 14" Hemlock, S81°E, 16.0'

13-Sec.14 Bearings: 9" Cedar, N24°E, 9.8' and 9" B. Spruce, S21°W, 5.8'

SIGNED BY Billy D. Buckler

DATE 10-30-74

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____

CHIEF OF SURVEY PARTY

DATE _____

APPROVED AND SIGNED BY _____

MICHIGAN REGISTERED LAND SURVEYOR

DATE _____

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM NO. 10-17-73
REVISED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

