MAY 2 8 1997

CHIPPEWA COUNTY REMONUMENTATION CORNER

COMMISSION

LAND CORNER RECORDATION CERTIFICATET, 00 LAND CORNER Filing Requirement of Act 74, Mich. P.A. 1970

Tor comers in		\$2.00 HSSR
Chippewa (County)	Located in: Corner Code #	3/4/1997 2:24:17 PM Receipt #294 RECEIVED FOR RECORD
1. Public Land Survey	T46N R 2W G-1/G-2	CHIPPENA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS
Property Controlling in Section	s_ T_R #5	BOOK 10 PAGE 81
3. Miscellaneous Property in Sec.	S TR S TR	Register of Deeds Stamp & File Number

4. LOT NO,	Recorded Plat
5. Private Claims _	
_	

, in a field survey on $\frac{\text{Nov.}}{27}$ William L. Karr $_{\tt ,}$ 19 $^{\underline{96}}$ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in component with the corner points mentioned in lines 3, 4 and 5 above were in component with the corner points mentioned and surveyors or by a Decree of a Court of Law; established, re-established, months recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be on this certificate.

A. Description of original monument and accessories and/or subsequent restoration.

(G-1/G-2) Witness Corner to the Meander Corner Common to Sections 3 & 4, T.46 N., R.2 W.

1849: H. Mellen set M.C. post 2562.12' North of 1/4 corner 3 & 4

1930: C.M. Cade in survey of State Park shows a distance of 2025.6 (may be in error) from 1/4 corner 3 & 4 North to a 4" x 4" concrete monument.

1947: R.H. Larsen shows a concrete monument at the Northwest corner of Lot 29, Supervisor's Plat of Bay Mills and Superior Townships (L. 6, Pg. 1 of Plats).

1990: L.R. Rogers, P.S. 29251 in a survey of Lot 29 of the Supervisor's Plat No. 1, indicates the Northwest corner of Lot 29 has been removed and that there is a large drainage ditch along the Section line.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G-1/G-2) This Corner is being re-established as part of of the Chippewa County Remonumentation Program.

Found no evidence of original corner. Re-constructed the Northwest corner of Lot 29 based on interior plat information. This mathmatical position falls 0.04 East of a line from 1/4 corner 3 & 4 projected thru a found concrete monument at the North 1/16th corner position. Distance from 1/4 corner 3 & 4 to the mathmatical position is 2528.38'. 1/2" x 48" irons were set at 90° and 15.00' East and West of this mathmatical point.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G-1/G-2) Corner is a mathmatical point which falls in 10' wide ditch. All witnesses were computed and referenced to this mathmatical point.

Witnesses:	West end steel break wall 1/2" x 48" iron South end chain link fence 1'2" x 48" iron	N11°E East S48°W West	4.34' 15.00' 18.55' 15.00'
	1-1/2" iron pipe	Nee _o M	15.67'
	_		

Surveyor's Michigan License No. NOTE: All bearings are compass bearings corrected

for declination. All distances are to a nail in side of witness objects us

REVISED MAY 14,1975 REVISED JAN., 1983

KARR LAND SURVEYOR No 27450