

MAR 6 2 1999

1998 CHEBOYGAN COUNTY REMONUMENTATION

SECTION		D CORNER RECORDATION CE		
For corners in	Fili	ing Requirement of Act 74, Mich.	. P.A. 1970	
Cheboygan				~ <i>C</i>
	Located in:	Corner Code #	RECEIVED FOR RECORD /-	<u>7</u> 7
(County)			RECEIVED FOR RECORD 1-8- at 9:01 0'Clock A	_M
1. Public Land Survey	T36N R	3W <u>E-1</u>		
•	T <u>37N</u> R	$\overline{3W}$ $\overline{E-13}$	(James Small)
	<u>TR</u>	`~~~~~	Janen Spring	
2. Dramanti Cantrallina	TR			
2. Property Controlling in Section	S IR		CLERK/REGISTER	
3. Miscellaneous	S T R	· · · · · · · · · · · · · · · · · · ·	CHEBOYGAN COUNTY, MICHIGAN	
Property in Sec.	S TR		Pagister of Doods Stown & Ella	Missanhana
			Register of Deeds Stamp & File	Number
4 Lot No. Peco	rded Dist			
5. Private Claims	ided Flat		A B C D E F G H I J	KLM
			<u> </u>	
			2 6 5 4 3 - 2	:
Brian K. Fullford	in a feld a	June 4698		
requirements of P.A. 74. Michia	, in a πexisurvey on an PA of 1970 the com	June , 19 ⁹⁸ do hereby state the ner points mentioned in lines 1 and 2 above	hat under 4 7 8 9 10 10 1	1-12
conformance with regulations and	o ruies inereiore as requir	red in the current manual of survey instructio	onsofthe "	
United States Department of the	Interior, Bureau of Land I	Management or by a decree of a Court of Law e were in conformance with the rules of the I	w and /or 6 18 17 16 15 15	41/3
Board of Land Surveyors or by	y a Decree of a Court	of Law; established, re-established, monu	umented, 7	+
recovered, found as expressed by	elow:	•	8 19 20 21 22 2	324
NOTE: Not more than 2 con	ners, all in the same tov	9		
on this certificate.		, , , , , , , , , , , ,	10 30 29 28 27 2	6 6 25
			11	
			12 -31 32 33 34 35	536
			13]
A. Description of original mo	onument and accesso	ries and/or subsequent restoration:	13	
		•	·	
1840 John Mullett		Sept 1976 Herbert Fluharty		
Original Survey		#18223		
Set post 6" Pine N 7° W 12 lk	rs (7 02')	Fnd 1" pipe @ intersection		
8" B. Oak N 32° E 6	.5 (1.32) 8 lks	brush line N & S and Old Trail E & W		
(44.88')		9" Oak S 20° W 16.96'		
(),,,,,		11" Oak N 60° W 40.90'		
		7" Oak N 52° E 34.71'		
B. Description of corner evi	dence found and/or m	nethod applied in restoring or reestablis	shina corner:	
·		.,		
Fnd 1" pipe on N & S	S brush Line			
11" Triple Oak N 52				1
14" R. Pine S 16° E		ze		j {
13" Oak S 20° W 16			وروسه های از این از در	
14" Oak N 60° W 40	.98' w/ blaze		Jana H dran	
				ا
				<i>'</i>
				. n
Description of manument	for corner and access	sories established to perpetuate locating		
o. Description of montanent	tor comer and access	sones established to perpetuate tocating	ig the position of the corner:	
E-1 Placed 5/8"	rebar with remonur	nentation cap inside pipe, and pos	sition is accepted as a careful and	
faithful perp	etuation of the origi	nal corner.		
_	Ide Tumbo October	9 17 04 701 0 21 11000	white OF Mich	t.
	I1" Triple Oak N 52 I4" Red Pine S 16°	_	ANTE OF MICHAEL	
	13" Oak S 20° W 16		A CONTRACTOR	
	13 Oak 0 20 W 10 14" Oak N 60° W 40		** BRIAN K. * FULLFORD	4 " 3
			Em I ODOCECCIONAL	i z i
NOTE: THIS CORNE	K IS ALSO DESI	GNATED AS CODE E-13 IN T3	37N-R3W. ₹Ω surveyor	<i>**</i>
	TAI)		No.	123

LIBER 011 FACE 119

OFESSIONA