FELIONUMENTATION

FEB 2 2 1996

COMMISSION

K-5 [NW COR S.13]

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Land Survey Remonumentation Peer Group Under Act 345 Of Of 1990 On______, 199 , 199<u>6</u> Of 1990 On

Approved by Delta County

acting Chairman

For corners in DELTA		1	00-4		
1.	(County) Public Land Survey	Located In:	Corner Code ## K-5 & F-1	Recorded (8	1996 8 page 126
•	, 30.10 23.12 00.10,	T R T R T R			Reg. of Doods.
2.	Property Controlling in Section	S T R S T R			
3.	Miscellaneous	S T R		Register of Deeds Stamp	& File Number
	Property in Sec.	S T R			
4.	Lot NoBe	eerded-Plat		ARCDEF	G H I J K L !
5.		1 [N1/4 COR S.4 - SAME AS F-	13 T39NR24W]	2 6 5 4	3 - 2 - 1 -
I, _	M.P. DAVIS	in a field survey on4/94	& 12/95 , 19 <u>9</u>		10 11 12
in	lines 1 and 2 above were in	conformance with regulations a	A. of 1970, the corner points ment and rules therefore as required artment of the Interior, Bureau of	in the	15-14-13-
cu Ma	rrent manual of survey instruc inagement or by a decree of a	Court of Law and/or that the corr	ner points mentioned in lines 3, 4	and 5 8 19 20 21	22 23 24
ab	ove were in conformance with	the rules of the Michigan Board	l of Land Surveyors or by a Decre	ee of a	
	ourt of Law; established, re pressed below:	-established, monumented, re	-monumented, recovered, four	10 30 29 28	272625-
NC	OTE: Not more than 4 co on this certificate.	rners, all in the same town a	and range, may be recorded	11	34-35-36-
A.	Description of original m	nonument and accessories a	nd/or subsequent restoration		

GEORGE ADAIR, D.S. - 1852- WOOD POST - (CEDAR 18"-N37"W-32 LINKS) (CEDAR 11"-S38"E-05 LINKS) F.BRAY-M.D.N.R.-1973-ESTABLISHED COR POSITION BY DOUBLE PROPORTIONATE DISTANCE FROM CORNERS 1 Mi N-W-E & 1/2 Mi SOUTH

- F-1 [N1/4 COR S.4] WOOD POST JAMES H. MULLETTE, D.S. 1848 (CEDAR 12"-N02°E-31 LINKS) (FIR 6° -N37°W-48 LINKS) D.A. BROTHERTON-1910-IDENTIFIED CORNER POSITION FROM ORIGINALS-NOTED NEW BT (SPRUCE 9"-S55'E-18.0')
- Description of corner evidence found and/or method applied in restoring or reestablishing corner: K-5 [NW COR S.13]

SET 1-1/2" I.P. (CEDAR 5"-S14"W-28.5') (CEDAR 4"-N50"W-53.0') REC'D IN LCR'S L.1 PAGE 373

FOUND 1-1/2" IP IN PLACE - BENT & IN POOR CONDITION - ID CORNER MONUMENT FROM BOTH CEDAR BT'S SHOWN IN LCR'S L. 1 PAGE 373 - BOTH BT'S STILL GREEN

F-1 [N1/4 COR S.4] TRAVERSED WEST FROM NE CORNER OF SEC 4 TO APPROXIMATE CORNER POSITION AS 1D FROM THE RECORDS OF D.A.BROTHERTON AT WHICH POINT I FOUND A 11/4" I.P. AT THE APPROXIMATE "GLO" DISTANCE WEST OF THE EAST BRANCH OF THE BARK RIVER, IN LINE WITH AN ANCIENT FENCE (DOWN & IN POOR CONDITION AND CLOSE TO BROTHERTON'S DISTANCE WEST OF THE NE CORNER OF SEC 4. NO EVIDENCE OF THE "GLO" CEDAR BT AS MENTIONED IN BROTHERTON'S NOTES OR OF HIS SPRUCE BT. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE POISTIION OF THE ORIGINAL CORNER.



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - K-5 REPLACED EXISTING IP W/A 5/8" X 18" REBAR W/A 3-1/4" ALUMN CAP STAMPED TO ID THE CORNER POSITION.

CEDAR 8° CEDAR 9" CEDAR 7" CEDAR 7" SURVEY MONUMENT SIGN POST N48°W N70°E \$50°E S14°W SOUTH 53.25 58.45 38.62 28.51 10.15' (TO FACE)

F-1 SET, OVER EXISTING MONUMENT, A BERNTSEN AINB30 ALUMN MONUMENT W/A 31/4" CAP STAMPED TO ID THE CORNER POSITION.

DRY CEDAR 13" DRY CEDAR 7" CEDAR 13" SURVEY MONUMENT SIGN POST N82°W S74°E \$43°W NORTH 30.75' 12.55 10.58 2.61' (TO FACE)

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC - DISTANCES ARE TO A MAIL IN THE CENTER OF THE OBJECT UNLESS NOTED OTHERWISE

Signed by A.P. Specia	· · [Date JANB, 1996
Surveyor's Michigan License No	16926	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197