## SURVEY & REMONUMENTATION

FEB 02 1999

L,	and t	Survey	Hemo	nume	ntation	
	Peer	Group	Under	Act 3	45 Of	
P.A.	Of 19	190 On	Deroue	les 3	<i>Q</i> . 199	8
		اصد			,	_

Chairman

Approved By Delta County

r	~ ``	~	1	10	3
_			О	1	ď

Private Claims \_\_\_\_

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

curtos D	in 4	1999
3:40	o'ctock P	M
$\wedge$		

For corners in DELTA Located In: Corner Code ## Ro **Public Land Survey** T 40 N R 19 W (-4MC - G-8/9 (16) T 40 N R 19 W \_\_ R \_\_ \_\_ R \_ \_\_\_ R \_ 2. Property Controlling Τ\_\_ \_\_ T \_\_\_\_ R \_ in Section \_ R \_ Miscellaneous \_ T \_\_ Property in Sec.

Register of Deeds Stamp & File Number

G-4 [WI/4 COR SEC 10] G-8/9 [M.C. SEC 9/10] DECEMBER . in a field survey on do hereby certify that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land

\_\_ , Recorded Plat \_

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: G-4 [W1/4 COR SEC. 10] A.MERRYWEATHER, D.S. - 1848 - WOOD POST (TAMARACK 12"-CORNER TREE) M.S.McNABB - 1919 - NO CORNER TO BE FOUND - RESTORED FROM "GLO" DISTANCE SOUTH TO SWAMP EDGE & SPRUCE SIGHT TREE, (CEDAR 08" NO5°E 13.2')(BIRCH 10" S65°E 20.7')

G-8/9 [M.C. SEC 9/10] A.MERRYWEATHER, D.S. - 1848 - WOOD POST (CEDAR 10\* \$40°N 57 LINKS) H.S. Henabb -1925 - Large Cedar Stake in Place, Set I.P. (Cedar 06" N75'E 9.5') "This corner found at gov. distance south of 1/4 CORNER AND 285' NORTH OF PRESENT SHORE.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: G-4 [W1/4 COR SEC. 10] FOUND IN PLACE REMAINS OF POST POINT BURIED 6" BELOW GRADE. ID MONUMENT AS THAT SET BY M.S. McNABB IN 1925 FROM HIS CEDAR BY NE STILL GREEN AND W.BIRCH BY SE WHICH IS NOW A WELL DETERIORATED STUMP. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.
  - G-8/9 [M.C. SEC. 9/10] FOUND IN PLACE MCNABB'S 1925 IRON PIPE 285' M/L NORTH OF PRESENT SHORE AND AT APPROXIMATE "GLO" DISTANCE SOUTH OF THE 1/4 CORNER TO THE NORTH. MCNABB'S CEDAR BY NOW ONLY A STUMP IN THE ADVANCE STAGES OF DECAY, INDENTIFIABLE ONLY BY ITS' RELATION TO THE EXISTING MONUMENT. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.



C.	Description of monument for	or corner and	accessories e	stablished to r	perpetuate locating the position of the corner:	
					STAMPED TO ID THE CORNER POSITION.	
	CEDAR 16" (OLD BT)	CEDAR 09"	CEDAR 08"	CEDAR 08*	SURVEY MONUMENT SIGN POST	
	N05°E	S68°E	S12'W	N69°W	NORTH	
	13.60'	33.31'	21.24'	18.43'	1.37' (TO FACE)	
			•		`	
	G-8/9 SET. OVER EXISTING MOD	IUMENT. A BERN'	ISEN A1NB30 AI	JUMN MON. W/A 3	31/4" CAP STAMPED TO ID THE CORNER POSITION.	

CEDAR 06". CEDAR 10\* CEDAR 06" SURVEY MONUMENT SIGN POST S10°W S53°E N24°W NORTH 15.02 60.44 31.35 1.37' (TO FACE)

												•						
NOTE:	BEARINGS	T0	REFERENCE	OBJECTS	ARE	MAGNETIC	-DISTANCES	ARE	10	NAIL	W/A	DELTA	COUNTY	REFERENCE	TAG,	UNLESS	OTHERWISE	NOTE

16926 Surveyor's Michigan License No. \_\_\_