RECORDED

LAND CORNER RECORDATION CERTIFICATE
Esting Requirement of Act 74, Mich. P.A. 1970

1799 DEC 11 11 12: 24

	Filing Requirement of Act	. 74, WIIGH. F.F	1010
For corners in		;	
	County)	•	REGISTED OF DEEDS DICKIESON COUNTY OF PONTHUM
Breitung 1, Public La	T_40NR_30W A-2 V T_R B-5 T_R		SURVEY & REMONUMENTATION
2. Property in Section	n <u>STR</u>	- 	APR 0 2 1999
3. Miscellar Property		-	Register of Reeds Stamp & File Number
5. Private C	Recorded Plat		A B C D E F G H I J K L M 2 6 5 4 3 2 1 1 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
requirements conformance to United States that the corne Board of Lar recovered, fou	F. Perkins., in a field survey on Aug. 18, 1998 do of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines with regulations and rules therefore as required in the current manual of a Department of the Interior, Bureau of Land Management or by a decree of a points mentioned in lines 3, 4 and 5 above were in conformance with the discoveryors or by a Decree of a Court of Law; established, re-estant as expressed below:	curvey instructions of a Court of Law a he rules of the Mic ablished, monum	of the and /or 6 19 17 16 15 14 13 bhigan
NOTE: No	t more than 2 comers, all in the same town and range, may be rec this certificate.	orded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36 13
A. Descrip	tion of original monument and accessories and/or subsequent r	estoration;	$\frac{7}{10}$
A-2	West ! Corner Section 6 Post by H. Brevort, D.S. 1848 Original Bearing Trees Aspen 3" S15°E 04 Lk. Cherry 3" N80°W 08 Lk. 1978 E.C. Muller, P.S. & E. Kaziaka, P.S. find 3/4" Iron Rod in Road Centerline and Record same on Certificate #181.	B-5 S.	L' Corner Common to Sections 18 Post by James H. Mullett, D.S. 1849 Original Bearing Trees Birch 3" S44°E 24 Lk. Birch 3" S60°E 20 Lk.
B Descri	ption of corner evidence found and/or method applied in restori	ng or reestablish	ning corner:
A-2	No Evidence of Original Corner or its Accessories Found. Found 1978 Bearing Trees: Oak 5" N16°E 46.87' Maple 6" S21°E 13.47' (Stump & Nail) Failed to find 3/4" Iron Rod. Probably Lost in Road Construction.	в-5	No Evidence of Original Corner or Accessories Found. Found 1" Sq. Iron Bar with 2 Existing BT's as Noted on Old Corner Report #826 by J. Smallwood dated 4-16-64.
C. Descrip	ption of monument for corner and accessories established to pe	erpetuate locatin	g the position of the corner:
A-2	Set 31" Stamped D.C. Remon. Corner from 2 Found 1978 BT's Noted in B.	в-5	Accepted above Iron Bar as Best Remaining Evidence and replaced same with 21" Stamped D.C. Remon. Corner.
	New Witnesses P.Pole #85-22742 N48°W(M.B.) 24.94' Nail P.Pole #85-22709 S18°W(M.B.) 57.50' Nail Oak 5" N16°E(M.B.) 46.87' Ex. B.T. Set 2½" Stamped D.C. Remon. Witness Corn 30.00' South.	ner	New Witnesses Hemlock 5" SO8°W 4.27' Nail/Tag Cedar 8" S56°W 22.13' Nail/Tag Maple 3" S48°E 16.93' Nail/Tag W.Pine 24" S86°E 9.41' Ex. B.T. Flaced Carsonite Marker 1' South.
-11111	Set Carsonite Stake at W.C.	eeroon	Placed Carsonite Market 1 South.

COUNTY REPRESENTATIVE

Liber 2 Page 394

Oct. 24,