## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Dickinson	Located In:	Corner Code #	
/AUCEDAH TOWNSHIP . Public Land Survey	T 41N R 28W T R R	E12	
Property Controlling a Section	S T R 28W S T R	16	
. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
I. Lot No, Rec i. Private Claims	orded Plat6/17/20	214	A B C D E F G H I J K L 1 2 6 5 4 4 3 2 1 1
Jeremy J. Pipp , in	<del>-</del> ,,,		e 3
bove were in conformance with restructions of the United States D	74, Michigan P.A. of 1970, the corner regulations and rules therefore as requi Department of the Interior, Bureau of	ired in the current manual of surve Land Management or by a decree o	vey 5 of 6 -18 -17 -16 -15 -14 -13 -
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with he rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, e-established, monumented, recovered, found as expressed below:			
Not more than 2 corns in this certificate.	ers, all in the same town and rang	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36	

- $\iota$ . Description of original monument and accessories and/or subsequent restoration:
- (E12) Quarter corner common to Sections 32 and 33. 1850: John Burt, DS. Set Sugar quarter section corner post witnessed by Cedar 12 S69W 16 links (10.56'), Sugar 12 N65E 46 links (30.36'). 1958:
  Michigan DNR (Billy Buckler PS#8887) Set 1" pipe with 4" Brass cap witnessed by 6" Hard Maple S63W 32 links (40.92'), 5" Hard Maple S88E 14 links (9.24'). 2001: Coleman Engineering (James H. Moore, 'S#28423) accepted found monument and created additional witnesses, 7" S. Maple N82W 21.74', 10" S. Maple NO7W 8.35', EX. 14" S. Maple S89E 9.95', 6" Aspen S15E 28.79', Carsonite Marker West 1.0'.
- (16) East One-Sixteenth corner common to Sections 30 and 31. Not set in original survey, no evidence of subsequent establishment.
- 3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (E12) Accepted found MDNR Monument and remains of Four NBT Witnesses (all dead; maples were cut. ooplar dead and down). Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner.
- (16) Corner position established mid-point and on-line between the South One-Quarter corner and the Southeast corner of Section 30.

(16)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E12)	DNR mo	nument				
16" Maple	N8	8E 130.1	' (1/4S,NBT)			
4" Spruce	S3	7E 28.43	' (1/4S,NBT)			
5" Spruce	N5	1W 58.18	' (1/4S,NBT)			
7" Spruce	N3	6W 63.88	' (1/4S,NBT)			
All trees	are blaz	ed, scrib	ed, painted,			
and signed. Measurements are to nail in						
side of tree, bearings are magnetic.						
Found Carsonite rail was West 1.0 feet. /.						
Signed by		1	reems .	1		

N44E 13.57' (1/16S,BT) 10" Maple 12" Maple S46E 17.24' (1/16S,BT) 4" Maple 7.52' (1/16S,BT) S55W 6.81' (1/16S,BT) 12" Maple N15W All trees are blazed, scribed, and paints. Officeral ments are to nail in 🍇 gs are magnetic. July 15, 2014

DNR monument

EREMYDate

Surveyor's Michigan License No. **5**044 For the Mirnigan Department of Natural Resources

PIPP

TATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975

20373 20374