

**LAND CORNER RECORDATION CERTIFICATE**  
**FILING REQUIREMENT OF ACT 74, MICH. P.A.1970**

FOR CORNERS OF--:	(DICKINSON COUNTY) LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>41</u> N. <u>X</u> R. <u>28</u> <u>X</u> W.	<u>B-5</u>
2. PROPERTY CONTROLLING IN SECTION <u>7</u>	T. <u>41</u> N. <u>X</u> R. <u>28</u> <u>X</u> W.	<u>13</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ R. _____ E. _____ W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		
		REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on see below, 19\_\_\_\_, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

**Corner B5 (1/4 corner between Section 7 & 18, T41N, R28W):**  
Cedar post (Not found. No subsequent monuments found.)  
Spruce 10 S36E 24 (Not found. No subsequent accessories found.)  
Cedar 12 N56W 28 (Not found. No subsequent accessories found.)

**Corner 13 (Center of SE 1/4, Section 7, T41N, R28W):**  
Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

**Corner B5:** Restored 8/22/77 proportionately on line between Sec. Cor. 40.023 ch. E and Sec. Cor. 41.024 ch. W. Position checks with swamp edge to E, but not with stream to W, leading me to the suspicion that the west 1/2-mile was never actually run in the original survey, the 1/4-section corner being established 40.00 ch. W of the sec. cor. to E. I have uncovered evidence of this procedure on other lines in the vicinity, particularly the section line between Secs. 8 & 17.  
**Corner 13:** Established 11/4/77 at computed intersection of quarter-quarter section lines, the lines of reference being from the S1/16 cor. bet. Secs. 7 & 8 and the E1/16 cor. on E-W 1/4 line of Sec. 7.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**Corner B5:** 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.  
B. Spruce 6 S21°E (mag.) 3.6 ft. "1/4S, NBT"  
Cedar 11 N83°E (mag.) 48.2 ft. "1/4S, NBT"  
Declination is 3°50' West.

**Corner 13:** 1" I.D. x 36" iron pipe with 3 3/4" aluminum cap.  
Red Maple 5 N86°W (mag.) 24.8 ft. "1/16S, BT"  
B. Ash 3 N67°E (mag.) 15.1 ft. "1/16S, BT"  
Declination 4°10' West.

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY Arthur O. Enger DATE August 14, 1978  
CHIEF OF SURVEY PARTY  
MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger  
Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

