

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
Dickinson

(County)

Located In:

Corner Code #

1. Public Land Survey	T	41N	R	29W	83
	T	41N	R	29W	C1
	T		R		
	T		R		
2. Property Controlling in Section	S	6	T	41N	R
	S		T		R
3. Miscellaneous Property in Sec.	S		T		R
	S		T		R

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

I, Stephan J. Szyszkoski, in a field survey on August 26, 1992, 19\_\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

**A. Description of original monument and accessories and/or subsequent restoration:**

(83) Quarter corner common to Sections 6-7. Corner established by U.S. Deputy Surveyor John Burt, 1849. Original BTs: Cedar 10 S47W 30, Hemlock 14 N33E 10. Found no subsequent record.  
(C1) Section corner common to Sections 5-6 T41N-R29W and Sections 31-32 T42N-R29W. Original corner established by U.S. Deputy Surveyor Wm. A. Burt, 1849. Original BTs: Hemlock 6 N05E 58, Y. Birch - N00W 39. Found no subsequent record.  
(4) Witness corner to the Northwest 1/16 corner of Section 6, T41N-R29W. Corner not established in the original survey. Found no subsequent record.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

(83) Original post and accessories not recovered. Determined corner to be lost and reestablished the corner by single proportionate measure to the original record between monumented corners 2583.79' east and 2696.84' west. About 60' west of the corner, found a probable Hanna Mining Co. monument, disturbed, at the base of a small ledge, from which it had fallen, and a blaze on a 20" poplar facing it. It appears that this mining co. monument was placed 2640' from the section corner to the east. A mining co. witness pipe was found adjacent to the poplar. Both the witness pipe and the brass capped monument were removed and placed next to the reestablished corner. Found a 5/8" iron pin w/brass tag #6307 wired on - apparently an old mining co. traverse station, S08E 27.6' from the corner.  
(C1) Original post and accessories not recovered. Corner falls in old Groveland mine tailings pond. Found no other evidence on the ground. Reestablished the corner by single proportionate measurement to the original record between recorded section corners 5291.48' east and 5407.24' west.  
(4) Found no evidence of previous monumentation. Established this witness corner on a straight line connecting 1/16 corners 83 and 85, 240.00' west of the northwest 1/16 corner of Section 6 (corner #4). Corner 83 is monumented. The positions of all other 1/16 corners were computed, their location determined by the current BLM instructions for the subdivision of regular sections.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

(83) Placed a 1"x30" iron pipe capped with a 4" dia. cast aluminum HDNR tablet. Blazed and scribed the following new bearing trees:  
7" Y. Birch S41W 11.6' (1/4S NBT)  
19" V. Pine S64W 56.4' (1/4S NBT)  
28" W. Pine N64W 10.0' (1/4S NBT)  
Placed a sq'd ash post N05W, 1.7' from the corner.

(C1) Placed a 1"x36" iron pipe capped with a 4" dia. cast aluminum HDNR tablet from which bears four 1.75"x8' iron pipes, set approximately 3.5' in the ground as follows:  
N15W 4.7', N79E 4.7',  
S12E 4.8', S82W 4.7'.  
The southeast toe of slope of the tailings pond embankment (course S55W) bears N35W, 194' distant.

(4) Placed a 1"x32" iron pipe capped with a 4" dia. cast aluminum HDNR tablet stamped "Witness Corner NW1/16 Sec. 6 240.00' East".  
Blazed and scribed the following BTs:  
5" W. Birch S08E 15.2' (WC BT)  
7" Maple S38E 25.5' (WC BT)  
5" W. Birch S77E 63.5' (WC BT)  
Placed 3" Maple post West of  
East 26', Intersecting pond

Signed by

Stephan J. Szyszkoski

Date 1-12-93

Surveyor's Michigan License No.

33986

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN 22 1971

