LAND CORNER RECORDATION CERTIFICATE

For corners in	riung	g requirement of Act 74, Mich. P.A	L 1970						
Dickinson (Course)	Located in:	Corner Code #							
1. Public Land Survey	T418 R 2 T418 R 2 TR	29N KII							
Property Controlling In Section Miscellaneous Property in Sec.	STR_ STR_ STR_			rogista	r of D	eeds S	tamp å	L File N	u mbe r
4. Lot No, Reco	rded Plat	-	1 Å	ВС	D	E F	G H	I J	K L
		Sep 14 1998 Sep 09 1998	2	- 6-	- <u>\$</u>				+1
requirements of P.A. 74, Michigi conformance with regulations and United States Department of the that the corner points mentioned	, in a field survey on _ an P.A. of 1970, the comes d rules therefore as required interior, Bureau of Land Mis in lines 3, 4 and 5 above w y a Decree of a Court of	, 19 do hereby state that ur r points mentioned in lines 1 and 2 above wer f in the current menual of survey instructions of magement or by a decree of a Court of Law and were in conformance with the rules of the Michi Law; established, re-established, monumen	nder 4 e in 5 the 5	18	- 6 - -17- -20-	-16	15-	11	13
NOTE: Not more than 2 corr on this certificate.	ners, all in the same town	and range, mey be recorded	9 10 11 12	-30		33-	27-	26-	25
		s and/or subsequent restoration: ablished in 1849 by John Burt: "North	13 L	ctions	25 &	264	1 [0.00 Si	<u> </u>	J ock

Or. Sect. post. Hemlock 18 NSOE 25, Hemlock 10 S48N 18."

(X11) Corner common to Sections 25-26-35-36. Established in 1849 by John Burt: "North between Sections 35 & 36...80.00 Set Hemlock post Cor. of Sections 25, 26, 35 & 36, Y. Birch 14 M50M 35, Cedar 10 S8E 19."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(KIO) The Original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the corner midway and on a line of mean true bearing between Section corners 2620.10' north and south. At the position for the corner I placed a 1° IO x 32° iron pipe capped with a 4° dia. cast aluminum MDMR tablet, appropriately stamped, and set firm in a mound of rock. Corner placed and witnessed by B.Wheeler and D.Lampela, Baraga District Office.

(KII) Original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the corner by double proportionate measurement to the original record between monumented original corners 79.3967 ch. north (80.0 R), 39.6979 ch. south (40.0 R), 40.0504 ch. west (39.95 R), and 80.1240 ch. east (79.94 R). At the position for the corner I placed a 1" ID x 32" iron pipe capped with a 4" dia. cast aluminum MDMR tablet, appropriately stamped. Corner placed and witnessed by D.Lampela and B.Wheeler, Baraga District Office.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corners (K10) Set 1" pipe with 4" MDNR cap. (KI1) Set 1 pipe with 4 MDNR cap. Blazed and scribed the following: Blazed and scribed the following: 8' R. Pine M24W 27.25' "1/45 NBT" 7" Spruce N86W 4.3" "S26 NBT" 5" Maple MSSN 47.5' 9" Spruce South 14.6" "S35 HBT" ďο SZYSZKOSKI 5" \$pruce N89E 66.0' 12" Spruce M88E 37.0' "\$25 NBT" đo LAND 2" Spruce \$76W 14.1" 6" Maple N71W 31.5' "\$26 HBT" ďa SURVEYOR Placed a squared cedar post adjacent. Placed a squared cedar post adjacent. Bearings are magnetic. Distances to Bearings are magnetic. Distances are to notch in lower blaze. notch in lower blaze. AND

33986 Surveyor's Michigan License No.

For the Michigan Department of Natural Resources - Forest Management Division