## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

	L1		1			
Dickinson	Located In:	Corner Code #				
(County)						
1. Public Land Survey	T 42N R 28W T 42N R 28W	104 J05				
2. Property Controlling in Section	T R S T R S T R					
3. Miscellaneous	S T R		1			
Property in Sec.	STR					
4. Lot No. , Re-	corded Plat		Registe	D E F C		Number
	7/29/20	13AD	2 6-	╼╪╼┼╾┊╼		2
, Jeremy J. Pipp , i	in a field survey on 7/29/20	13AD do hereby state	3			+++
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2						1/1
above were in conformance with		<del>- -   </del>	<del>                                     </del>	<del>       </del>		
nstructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 19 17					15	1,4-1,3-
t Court of Law and /or that the o	th 7			<del>                                     </del>		
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established			d, 8 -19-1	_2021_	22	23 24-
re-established, monumented, recovered, found as expressed below:						
			10 30	_2928	27	26 25-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			11			1 12
			12 31	_3233	34	3536

A. Description of original monument and accessories and/or subsequent restoration:

(IO4) Quarter corner common to Sections 10 and 11. 1850: John Burt, DS. Set Cedar quarter section post witnessed by Spruce 8 S54E 30 links (19.80'), Cedar 12 N57W 24 links (15.84'). 1981: Michael Beltz PS#28404 Set 5/8" Rebar with plastic cap witnessed by 8" Cedar N62E 17.67', 4" Balsam S31E 17.56', 12" Spruce N14E 5.82', 10" Tw. Cedar S31W 9.19'.

(J05) Quarter corner common to Sections 11 and 14. 1850: John Burt, DS. Set Cedar quarter section post witnessed by Y. Birch 8 S26W 4 links (2.64'), Cedar 6 N23E 23 links (15.18'). 1966: Michigan DNR (Frank Bray PS#13575) Set 1" pipe with 4" Aluminum cap witnessed by 5" Spruce N30E 82 1/2 links (54.45'), 6" Balsam \$15W 48 1/2 links (32.01'). 1981: Mike Beltz Survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(IO4) Accepted found capped rebar and Four witnesses (two living and two others [SE Balsam is a stub, SW Cedar is tipout]) and drove MDNR Monument over the top of existing position. Position is accepted as a careful and faithful PERPETUATION of the position of the original corner.

(J05) Accepted found MDNR Monument and reamains of four existing NBT Witnesses (standing dead). Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(IO4) DNR monument	(JO5) DNR monument			
EX 14" Spruce NO9E 5.85' (1/4S,NBT)	10" W. Birch N50E 38.35' (1/4S,NBT)			
EX 10" Cedar N63E 17.88' (1/4S,NBT)	17" Cedar N61E 94.15' (1/4S,NBT)			
11" Cedar S66E 51.59' (1/4S,NBT)	6" Cherry \$34E 24.75' (1/4S,NBT)			
10" Cedar S25E 59.30' (1/4S,NBT)	6" W. Birch N23W 70.8' (1/4S,NBT)			
All trees are blazed, scribed, painted,	All trees are blazed, scribed, painted,			
and signed. Measurements are to nail in	and signed. Measurements are to nail in			
side of tree, bearings are magnetic. A	side of Heal Dearings are magnetic. A			
carsonite rail was set North 1.5 feet.	caretaite rair was set North 1.5 feet.			
Signed by leesen of	Date August 26, 2013			

9 50447

For the Michigan Department of Natural Resource

E BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975 Revised Jan., 1983

Rervised Oct., 1995

Surveyor's Michigan License No. /