			RUATION CERTIFIC								
For comon in	Filin	g Requirement of	Act 74, Mich. P.A. 19	970							
For corners in			. 1								
Dickinson	Located In:	Corner Code #									
(County)	,										
4. Dut to 1 and 0											
1. Public Land Survey	<u>T_43N_R_</u>										
	ŢR_										
	<u>TR</u> _										
2. Property Controlling	Ţ <u> </u>										
in Section	S TR_ S T R										
3. Miscellaneous	S TR										
Property in Sec.	S + P-										
r roporty in occ.	·			R	egiste	r of De	eds S	tamp 8	k File	Nur	nber
4. Lot No, Reco	rded Plat										
5. Private Claims				: A	ВС	D E	F	G H	I	J K	L I
				_ أ		_ []			1	Ĭ	1
		T 1.1.1000		2	ΪŢ	_ i _ i	_ i _			íΠ	_ i_
Abanka . Anasahadi		Jun 14 1999		3 ├	1-1			1-1-	+		
I, Stephan J. Szyszkoski	, in a field survey on	, 19,	do hereby state that under	4 🗕	· ? 	— ģ—Ì	 - _	10-	+-1	[1—	1 2
requirements of P.A. 74, Michiga conformance with regulations and	an P.A. of 1970, the come 1 rules therefore as require	r points mentioned in line d in the current manual of	es 1 and 2 above were in	5 -						\vdash	
United States Department of the	Interior, Bureau of Land M	anagement or by a decre-	of a Court of Law and /or	6	.1	_12_	16	L,!	,	لــا	
that the corner points mentioned	I in lines 3, 4 and 5 above v	were in conformance with	the rules of the Michigan	7 _	Ï		Ĭ		'	i	
Board of Land Surveyors or by recovered, found as expressed be	/ a Decree of a Court of	/ Law; established, re-e	stablished, monumented,	` [Ţ].				
recovered, round as expressed to	now.			8 -	19	-20 	—21—	-22-	1-7	3-	24
NOTE: Not more than 2 con	ners, all in the same towr	n and range, may be re	corded	9 📙	+-+			-			
on this certificate.		.		10—	-30	29-	28	27-	<u></u> 2	6	25
				-, <u>,</u> _							_
				11	1]		J.		<u> </u>	
				12	31-	-32	 	34- 1	 	1	36 I
of field book "Co. RD 12 Ralp appears to be (but is not lab by R.Perkins, dated 11/10/78	elled as) a represent	ation of the north 1	/2 of the N-S 1/4 lin	e of Se	ction	19. C	orner	shown	on a	surv	ey
B. Description of corner evid	cessories were not re	covered. Recovered	the Center of Section	19 and							ı
remonumented by Dickinson Co. falls about 12' east and 9' n Sec. 18, probably that shown on the Rd. Commission sketch notes, it being an incomplete reestablish this corner in ac 2698.40' W'ly and Section cor 1" IDx32" iron pipe capped wi	north of the subsequent on Perkins' drawing, and is not in accord record, and finding cord with them and so ther 2645.49' E'ly, be	tly reestablished po 40' east of the monu with the original re no monument whose p reestablish the cor ing proportionate to	sition. Recovered a mented position. Thi cord. Finding no spe osition is in agreeme ner on a line of mean the original record.	3/4" re s 3/4" cific r nt with true b At th	bar 27 rebar eferen these earing	37.96' does n ice to notes betwe	east ot fit a monu , I am en Sec	of the model the ment in the reluction continues.	SW ceasure n the tant orner	corne cemen co. to	ts Rd.
southwesterly Sugar in clump	t cap. ing: '1/4S MBT" do (being of 4) '4S MBT" acent.	ries established to per	rpetuate locating the po	STI SZN SU	EPHA (SZK) LANI IRVE) No.	OSKI O YOR					
notch in lower blaze.	tol 1 San	ahd.	D-1-	7/	MICHEL 7/0	O.	•				

33986

Surveyor's Michigan License No.