## LAND CORNER RECORDATION CERTIFICATE

Fo	or corners in Dickinson		, ,,,	uiA	uada	ur <b>d</b> erti	ent of ACt 74, Mich.	P.A. 19	70										
_	(County)		Located	ln:			Corner Code ≠#												
1.	Public Land Survey		Ţ																
			Ţ	R															
2.	Property Controlling	s 16 s 15	T 43N	A	291 291														
3.	Miscellaneous Property in Sec.	s 15	T 43N	P	\$ <b>9</b> 1			F	legisi	ter (	of D	eedi	s Sta	mp	4 F	ile !	Non	nbe	r
4.	Loi No , F	Recorded F	Plat							_					_		_		
5.	Private Claims								Ξ,	Ĵ.	<u>.                                    </u>	E T	-	╧	G	<u>"  </u>	╁╅	<del>"</del>	누
				4	Jun	e <b>8</b> 2,	1994			Ľ			土	上	Ľ			$\pm$	1
. 6	tephan J. Szyszhoski	in a flatri		. ,	Jun:	1 <b>85</b> ,	1994		4	╬	<u>}</u> _	┝╌	+	Ī.,	<u>_</u> ,	$\Box$	— <u>;</u> ;	7	_12
OO 1	hereby certify that under rec ines 1 and 2 above were in	:Quirements c	OI P.A. 74 N	dich i	ioan P i	A A 10	370 the corner coints ———		5	上			$\pm$	<u> </u>			<del> </del>	十	+
cun	rem manuel of survey instr	ructions of It	he United S	Stale:	is Deni	arimen	that Interior Revenue	of I would	,	Ĺ	Ц	Щ	I		Γï			ユ	-13- -
abo	nagement or by a decree of a We were in conformance will	ith the rules :	of the Mich	Naan	n Board	d of Lav	ad Surveyors or by a Decre	- 10 00		<u> </u>	<u> -</u>	<del> </del>	+;	۸⊣	<del>│</del> _₹	2-	—23 —23	4	-24-
eat)	urt of Law; established, r ressed below:	re-establish	ed, monur	nent	ed, re	-monu	imented, recovered, four	ind as	10			1	+	H	H		士	+	+
NOTE: Not more than 4 corners, all in the same town and range, may be recorde					inge, may be recorded	i	11	Ľ	П	$\ddot{-}$	T			$\Box$	<u>-26</u> ↓	丰	-25-		
	on this certificate.	•							12	Г,		—3 <del>2</del> -	┿	<b>5</b>	-34	4	-35	+	-36-
	Barret M. A. S. S.								13	ᆫ	L			Į.	L 1	. 1	- 1	- 1	

Description of original monument and accessories and/or subsequent restoration:

(2) Set 1' sine with 4' MONE can

(2-Sec.18) East 1/18 corner between Section 9-18. Corner not established in the original survey. Found no subsequent record.

(4-Sec.15) Berthwest 1/18 corner, Section 15. Corner not established in the original survey. Found no subsequent record.

(6-Sec. 15) Northeast 1/16 corner Section 15. Corner net established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(2-Sec.16) Found no evidence of prior monumentation at the corner position. Established the corner on a straight line between Quarter corner 1217.25' West and Section corner 1317.25' East. At the position for the corner, I placed a 1'I.B.x32' iron pipe capped with a 4" dia. cest gluminum MOMM tablet, appropriately stamped.

(4-Sec.15) found no evidence of prior monumentation at the corner position. Established the corner at the intersection of straight lines connecting apposite 1/18 corners, corners 21, 23, 25 being monumented, corner 28 a computed position midway between Center of Section and West 1/4 corner. At the position for the corner, I placed a 3"1.0.x32" from pipe capped with a 4" dim. cast aluminum MDAR tablet, appropriately stamped.

(6-Sec.15) Found no evidence of prior monumentation at the corner position. Established the corner at the intersection of straight lines connecting opposite 1/16 corners, all monumented. At the position for the corner, I placed a 1"I.D.x32" iron pipe capped with a 4" dia. cast aluninum MBMA tablet, appropriately stanged.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(2) Set 1" pipe with 4" NOMM cap. Blazed and scribed the following bearing trees:  3" Sugar \$320 5.8" "1/165 BT"  4" Sugar N640 2.9" "1/165 BT"  4" Sugar N24E 16.8" "1/165 BT"  3" Treewood \$54E 2.5" "1/165 BT" Found a forester's squared post 26" N. and 3" W. and reset adjacent to Donument. Bearings are magnetic.	(4) Set 1" pipe with 4" MDMR cap. Blazed and scribed the following bearing trees: 4" Balsam Fir 841E 9.0" "1/165 BT" 12" Balsam Fir 848W 28.2" "1/165 BT" 3" Balsam Fir NIOW 7.1" "1/165 BT" 5" Balsam Fir NSGE 33.8" "1/165 BT" Bet a squared 2" Birch post adjacent. Bearings are magnetic.	(6) Set 1° pipe with 4 Blazed and scribed the trosa: 6° Spruce 843E 33.9' 7° Spruce 817W 27.4' 9° Spruce 876W 40.1' 5° Aspen NOSW 14.3' Set a 3° squared balsas Searings are magnetic.	following bearing "1/105 BT" "1/105 BT" "1/105 BT" "1/105 BT" "1/105 BT" " post adjacent.
Signed by Surveyor's Michigan License No. 33	986 Date 7-1	•	STEPHAN J. SZYSZKOSKI- LAND SDRYEVID